





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA TWINAIR S
Colour	Red
Year of manufacture	2014
Top speed	117 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 2.000 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-01-29

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-08
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #10		2024-02-21 16:09
MOT test	number	762141112160
Result		✓ Passed
Next expi	ry date	2025-03-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Play in steering rack inner joint(s)	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

MOT #9	2024-02-21 11:56
MOT test number	767519864540
Result	🗙 Failed
Advice Play in steering rack inner joint(s)	
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))	

MOT #8	2023-02-16 16:34
MOT test number	725058114991
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2023-02-16 11:02

MOT test number 889733407986

Result X Failed

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

MOT #6 2022-02-17 10:25

MOT test number 824316273561

Result
✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2021-03-09 11:18

MOT test number 163746705977

Result \(\sqrt{Passed} \)

MOT #4 2020-08-03 09:59

MOT test number 938668751353

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))

CarCheck.co.uk page 4/12



MOT test number

211086294036

Result

Advice Nearside Rear door accident damage

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake cable damaged but not to excess outer sleeving broken (1.1.15 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2018-07-19 08:06
MOT test number	899869651667
Result	✓ Passed
MOT #1	2017-08-03 13:59
MOT test number	231778151782
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-25
Last registration	2024-02-21
Complete history	See info



Registration #1	2014-09-25	20 mi
Registration #2	2017-08-03	8.384 mi
Registration #3	2018-07-19	12.400 mi
Registration #4	2019-08-16	17.557 mi
Registration #5	2020-08-03	20.524 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number0252746