



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 SZ5
Colour	Black
Year of manufacture	2012
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	145 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-03-17
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	36
Total items failed	11

## MOT #14 2024-03-06 12:34

MOT test number 286427632387

Result ✓ Passed

Next expiry date 2025-03-17

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

## MOT #13 2023-03-13 11:30

MOT test number 422085629611

Result ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material all rear brake pipes (1.1.11 (c))

## MOT #12 2022-03-15 08:31

MOT test number 953977963660

Result ✓ Passed

**MOT #11** 2022-03-11 11:36**MOT test number** 980668089950**Result** ✗ Failed

**Advice** Rear Brake pipe corroded, covered in grease or other material both rear front to rear brake pipes (1.1.11 (c))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Front Brake pipe corroded, covered in grease or other material both pipes (1.1.11 (c))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2021-03-18 17:18**MOT test number** 187926363591**Result** ✓ Passed**MOT #9** 2020-06-19 11:02**MOT test number** 918569344719**Result** ✓ Passed**MOT #8** 2019-06-08 15:13**MOT test number** 677707335458**Result** ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7**

2019-06-08 11:02

**MOT test number**

726106409319

**Result****✗ Failed**

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Rear Service brake excessively fluctuating both sides (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm worn on the inner edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Rear Service brake excessively binding both sides (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm also worn on the inner edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #6**

2018-06-02 11:51

**MOT test number**

679777347757

**Result****✓ Passed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #5**

2017-06-29 09:02

**MOT test number**

962098345657

**Result**

✓ Passed

**Advice**

Both rear tyres cracked in the tread

**Advice**

Child Seat fitted not allowing full inspection of adult belt

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)

**MOT #4**

2016-06-28 11:02

**MOT test number**

346421379410

**Result**

✓ Passed

**MOT #3**

2016-06-27 15:23

**MOT test number**

971369777758

**Result**

✗ Failed

**Fail**

Brake pedal spongy (3.3.B.1b)

**Fail**

Nearside Front coil spring broken (2.4.C.1a)

**Advice**

Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2**

2015-01-21 15:02

**MOT test number**

615221625017

**Result**

✓ Passed

**Notice**

Advise cracks on front tyres

**Notice**

Child seat fitted not allowing full inspection of adult belt



MOT #12015-01-21 15:02

MOT test number258971425014

Result

Failed

Notice

 Advise cracks on front tyres

Pass with rectification

 Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

 Offside Headlamp aim too low (1.8)

Notice

 Child seat fitted not allowing full inspection of adult belt

Pass with rectification

 Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

 Nearside Headlamp aim too low (1.8)

Pass with rectification

 Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
17 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	17 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>SW61EXM</b>
Plate since	2020-03-29
Current registration	<b>SW61EXM</b>
Plate since	2020-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-01-20
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2012-01-20	12 mi
Registration #2	2015-01-21	17.545 mi
Registration #3	2016-06-27	21.956 mi
Registration #4	2016-06-28	21.960 mi
Registration #5	2017-06-29	26.614 mi
Registration #6	2018-06-02	31.645 mi
Registration #7	2019-06-08	38.390 mi
Registration #8	2019-06-08	38.390 mi
Registration #9	2019-06-08	38.390 mi
Registration #10	2019-06-08	38.390 mi
Registration #11	2019-06-08	38.390 mi
Registration #12	2019-06-08	38.390 mi
Registration #13	2019-06-08	38.390 mi
Registration #14	2019-06-08	38.390 mi
Registration #15	2019-06-08	38.390 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1730 mm
Height	1570 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1200 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1653502