



report date: 2024-03-29

General information

Make	JAGUAR
Model	XF D V6 S PORTFOLIO SPORTBRAKE
Colour	Grey
Year of manufacture	2013
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	271 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.0 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 2

Date 2021-06-11

Pictures 8

Listing price [View report](#)




source: autotrader.co.uk

Entry 1

Date 2021-06-08

Pictures 18

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-25
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	18
Total items failed	0

MOT #12	2023-06-26 13:37
MOT test number	763965255619
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn to the limit 1.6mm (5.2.3 (e))

MOT #11	2022-06-13 16:34
MOT test number	190207116034
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10**

2022-06-13 12:35

MOT test number

449357734231

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9**

2021-06-16 16:20

MOT test number

873602917836

Result**✓ Passed****MOT #8**

2020-09-04 12:59

MOT test number

431497745615

Result**✓ Passed****MOT #7**

2020-09-03 10:51

MOT test number

616085146737

Result**✗ Failed****DANGEROUS** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure outer wall (5.2.3 (d) (ii))**Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working centre high level stop lamp inoperative. (4.3.1 (a) (ii))**MAJOR** Front Windscreen washer not working inoperative (3.5 (a))

**MOT #6** 2020-09-03 07:45**MOT test number** 969991879085**Result** ✗ Failed**Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working centre high level stop lamp inoperative. (4.3.1 (a) (ii))**MAJOR** Front Windscreen washer not working inoperative (3.5 (a))**MOT #5** 2020-03-13 15:35**MOT test number** 257008046213**Result** ✓ Passed**MOT #4** 2019-03-12 09:54**MOT test number** 672331272379**Result** ✓ Passed**MOT #3** 2018-03-15 10:43**MOT test number** 856783762462**Result** ✓ Passed**MOT #2** 2017-03-16 07:47**MOT test number** 293271348458**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2016-03-16 15:23**MOT test number** 352872263349**Result** ✓ Passed**Advice** Undertrays fitted not allowing full inspection of underside of vehicle



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	OV13BPX
Plate since	2024-03-29
Current registration	OV13BPX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-04-18
Last registration	2023-06-26
Complete history	See info



Registration #1	2013-04-18	18 mi
Registration #2	2016-03-16	21.232 mi
Registration #3	2017-03-16	32.448 mi
Registration #4	2018-03-15	35.445 mi
Registration #5	2019-03-12	38.728 mi
Registration #6	2020-03-13	42.736 mi
Registration #7	2020-09-03	44.187 mi
Registration #8	2020-09-03	44.187 mi
Registration #9	2020-09-03	44.187 mi
Registration #10	2020-09-03	44.187 mi
Registration #11	2020-09-03	44.187 mi
Registration #12	2020-09-03	44.187 mi
Registration #13	2020-09-03	44.187 mi
Registration #14	2020-09-03	44.187 mi
Registration #15	2020-09-03	44.187 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1877 mm
Height	1468 mm
Length	4966 mm
Wheel base	2909 mm
Max. allowed weight	2440 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0712366306DT