



PEUGEOT

YDI20FO

report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER HDI S L1 850
Colour	White
Year of manufacture	2012
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	52.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2024-10-23
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	37
Total items failed	23

MOT #16	2023-10-24 12:27
MOT test number	848101174725
Result	✓ Passed
Next expiry date	2024-10-23

MOT #15	2023-10-11 07:25
MOT test number	267162160908

Result	✗ Failed
--------	----------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn inner & outer edges (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn outer edge (5.2.3 (e))
- Fail** Nearside Windscreen washer not working (3.5 (a))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #14**

2022-10-10 13:26

MOT test number

785726393567

Result

✓ Passed

Advice Rear brake pads getting low**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 195/65/15 91h (5.2.3 (e))**MOT #13**

2022-10-10 08:52

MOT test number

989230256862

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 195/65/15 91h (5.2.3 (e))**Advice** Rear brake pads getting low**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**MOT #12**

2021-09-27 15:46

MOT test number

678489627881

Result

✓ Passed

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #11**

2020-10-01 15:43

MOT test number

193725995488

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Spare wheel defective

**MOT #10**

2020-09-29 13:37

MOT test number

265195352545

Result

✗ Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Spare wheel defective

Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

Fail Horn not working (7.7 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

MOT #9

2019-04-24 15:06

MOT test number

771731273523

Result

✓ Passed

MOT #8

2019-04-17 13:41

MOT test number

699207098781

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Horn not working (7.7 (a) (ii))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #7** 2018-04-20 08:59**MOT test number** 770363358275**Result** ✓ Passed

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Nail in tyre

MOT #6 2018-04-16 16:09**MOT test number** 463307572711**Result** ✗ Failed

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2017-02-24 14:26**MOT test number** 831951132793**Result** ✓ Passed

**MOT #4** 2017-02-24 10:46**MOT test number** 385625710481**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #3 2016-02-10 15:25**MOT test number** 784183536759**Result** ✓ Passed**MOT #2** 2015-03-25 15:54**MOT test number** 945934185028**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-03-25 15:54
MOT test number	965194485069
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
26 January 2024

✓

MOT

Expires:
23 October 2024

Tax status	Expired at 26 January 2024
Days left	95 days too late
MOT expiry date	23 October 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-30
Last registration	2023-10-24
Complete history	See info



Registration #1	2012-03-30	7 mi
Registration #2	2015-03-25	26.273 mi
Registration #3	2016-02-10	33.192 mi
Registration #4	2017-02-24	44.115 mi
Registration #5	2017-02-24	44.115 mi
Registration #6	2018-04-16	55.579 mi
Registration #7	2018-04-20	55.696 mi
Registration #8	2019-04-17	65.541 mi
Registration #9	2019-05-20	75.377 mi
Registration #10	2019-05-20	75.377 mi
Registration #11	2019-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2019-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2019-05-20	75.377 mi
Registration #16	2019-05-20	75.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1834 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1440 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBEM0015681