



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO ML20 DCI
Colour	Grey
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	16.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-29
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-06
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #13	2024-03-07 16:01
MOT test number	940787989018
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Spare tyre defective
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))

MOT #12	2024-03-01 14:03
MOT test number	260252100473
Result	✗ Failed
Advice	Spare tyre defective
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11	2023-01-14 10:06
MOT test number	774236888102
Result	✓ Passed

**MOT #10** 2022-01-14 16:48**MOT test number** 425146246958**Result** ✓ Passed**MOT #9** 2021-12-31 12:50**MOT test number** 671919579079**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm below 1.6mm in centre of tyre (5.2.3 (e))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both headlights hazed (4.1.4 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn to 2mm (5.2.3 (e))**MOT #8** 2020-06-23 09:59**MOT test number** 348065957032**Result** ✓ Passed**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #7** 2020-06-23 09:59**MOT test number** 779482135914**Result** ✗ Failed**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Pass with rectification** Front Main beam tell-tale not working (4.9.1 (a) (ii))

**MOT #6** 2018-08-04 07:53**MOT test number** 980680121645**Result** ✓ Passed**MOT #5** 2017-07-14 13:29**MOT test number** 418353391289**Result** ✓ Passed**MOT #4** 2016-06-22 10:30**MOT test number** 226396904661**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-07-01 16:49**MOT test number** 339962785123**Result** ✓ Passed**MOT #2** 2015-06-29 16:02**MOT test number** 587390885119**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #1** 2014-05-22 08:53**MOT test number** 786862644171**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
-------------------	---------------------

Days left	307
------------------	-----

MOT expiry date	6 March 2025
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	BF11BAU
Plate since	2019-09-28
Current registration	BF11BAU
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-10
Last registration	2024-03-07
Complete history	See info



Registration #1	2011-06-10	15 mi
Registration #2	2014-05-22	30.599 mi
Registration #3	2015-06-29	34.974 mi
Registration #4	2015-07-01	34.974 mi
Registration #5	2016-06-22	49.507 mi
Registration #6	2017-07-14	52.644 mi
Registration #7	2018-08-04	53.555 mi
Registration #8	2020-06-23	59.574 mi
Registration #9	2020-06-23	59.574 mi
Registration #10	2020-06-23	59.574 mi
Registration #11	2020-06-23	59.574 mi
Registration #12	2020-06-23	59.574 mi
Registration #13	2020-06-23	59.574 mi
Registration #14	2020-06-23	59.574 mi
Registration #15	2020-06-23	59.574 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2133 mm
Height	1844 mm
Length	4213 mm
Kerb weight	1268 kg
Max. allowed weight	2077 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D194696