





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	C AMG C 43 4MATIC PREMIUM PLUS
Colour	Black
Year of manufacture	2017
Top speed	155 mph
0 - 100 km/h	4.9 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	270 kW / 368 HP / 396 BHP
Max. torque	520 Nm at 2.000 rpm
Engine capacity	2.996 сс
Cylinders	6
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	183 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 1

Date 2021-06-23

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-07-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #5	2023-07-22 08:46
MOT test number	380909349003
Result	✓ Passed
Next expiry date	2024-07-29

MOT #4	2022-0	7-23 10:30
MOT test	number 4115	570559551
Result		✓ Passed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))	

MOT #3	2021-07-30 14:12
MOT test number	336628307266
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2020-12-10 17:05

MOT test number 478925427802

Result \rightarrow Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1 2020-12-10 09:33

MOT test number 497335516335

Result X Failed

DANGEROUS Nearside Front Tyre has a tear, caused by separation or partial failure of its structure Inner sidewall (5.2.3 (d) (ii))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure Inner sidewall (5.2.3 (d) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
First licence fee (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-12-29
Last registration	2023-07-22
Complete history	See info



Registration #1	2017-12-29	22 mi
Registration #2	2020-12-10	24.786 mi
Registration #3	2020-12-10	24.786 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1810 mm
Height	1405 mm
Length	4696 mm
Wheel base	2840 mm
Kerb weight	1735 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27682330748973

CarCheck.co.uk page 11/11