



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D2 BUSINESS EDITION
Colour	Grey
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-11-15
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk



MOT history

MOT expiry date	2024-09-17
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	18
Total items failed	4

MOT #7	2023-09-06 11:33
MOT test number	486642039446
Result	✓ Passed
Next expiry date	2024-09-17
Advice	Nearside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #6**

2023-09-05 11:45

**MOT test number**

394846872245

**Result****✗ Failed****Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #5**

2022-08-26 15:35

**MOT test number**

200456955123

**Result****✓ Passed****Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords [Outer sidewall] (5.2.3 (d) (i))**Advice** Offside Rear Road wheel slightly distorted [Inner rim] (5.2.2 (c) (i))**Advice** Nearside Rear Road wheel slightly distorted [Inner rim] (5.2.2 (c) (i))**MOT #4**

2022-08-17 09:12

**MOT test number**

891863532496

**Result****✗ Failed****Advice** Nearside Rear Road wheel slightly distorted [Inner rim] (5.2.2 (c) (i))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords [Outer sidewall] (5.2.3 (d) (i))**Advice** Offside Rear Road wheel slightly distorted [Inner rim] (5.2.2 (c) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #3** 2021-09-09 09:25**MOT test number** 710517661840**Result** ✓ Passed**MOT #2** 2021-09-09 08:19**MOT test number** 325468375803**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #1** 2020-09-10 08:09**MOT test number** 416202239850**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX67OWJ
Plate since	2019-03-29
Current registration	YX67OWJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-18
Last registration	2023-09-06
Complete history	<a href="#">See info</a>



Registration #1	2017-09-18	18 mi
Registration #2	2020-09-10	62.073 mi
Registration #3	2021-09-09	78.208 mi
Registration #4	2021-09-09	78.208 mi
Registration #5	2023-09-06	78.208 mi
Registration #6	2023-09-06	78.208 mi
Registration #7	2023-09-06	78.208 mi
Registration #8	2023-09-06	78.208 mi
Registration #9	2023-09-06	78.208 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1617 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	2043168
---------------	---------