





report date: 2024-03-29

#### General information

Make	KIA
Model	CEED CRDI 2 ISG
Colour	Black
Year of manufacture	2018
Top speed	121 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	134 BHP
Max. torque	280 Nm at 3.000 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date	2022-01-24
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



## MOT history

MOT expiry date	2025-01-17
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	26
Total items failed	0

MOT #5		2024-01-18 11:15
<b>MOT</b> test	number	470964941389
Result		<b>✓</b> Passed
Next expi	ry date	2025-01-17
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)	))
Advice (b))	Nearside Headlamp has a product on the light source but not seriously	reducing light output (4.1.4

CarCheck.co.uk page 3/12



MOT #4 2023-07-20 09:33

**MOT test number** 651803092356

✓ Passed Result **Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Parking brake has free play / travel at bottom of application **Advice** Nearside Front forward wheel arch liner missing Advice Offside Rear Inner Nail in tyre Advice Clutch slave cylinder leaking fluid Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Engine oil slightly over filled Advice Offside Front forward wheel arch liner insecure and rubbing on wheel

MOT #3 2023-01-19 09:32

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT test number** 114698700499

**Result** 
✓ Passed

**Advice** Engine oil overfilled

**Advice** 

**Advice** Nearside Front forward wheel arch liner missing

**Advice** Handbrake has free travel at bottom of application

CarCheck.co.uk page 4/12



Advice

**Advice** 

Engine oil overfilled

LJ18XJV report date: 2024-03-29

**MOT #2** 2022-02-09 10:27

MOT test number 833364842759

Result ✓ Passed **Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge and perished between treads (5.2.3 (e)) **Advice** Handbrake has free travel at bottom of application Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge and perished between treads (5.2.3 (e))

MOT #1 2021-02-23 10:35

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT test number** 526931787541

**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	17 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
HARMAN CO. C.	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NE AIR
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-09
Last registration	2024-01-18
Complete history	See info



Registration #1	2018-03-09	19 mi
Registration #2	2021-02-23	29.496 mi
Registration #3		11.777 es
Registration #4	2022-02-09	39.790 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 esi

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	2035 mm
Height	1485 mm
Length	4505 mm
Wheel base	2650 mm
Kerb weight	1529 kg
Max. allowed weight	1920 kg

# Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12