





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	White
Year of manufacture	2013
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	355 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	36.7 mpg
Consumption combined	34.0 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	19
Total items failed	6

MOT #11	2024-03-08 11:32
MOT test number	953808056880
Result	✓ Passed
Next expiry date	2025-03-07

MOT #10	2023-09-07 09:30
MOT test number	981060090887
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2023-03-10 11:31
MOT test number	751157788436
Result	✓ Passed
MOT #8	2019-06-18 14:53
MOT test number 5536899	
Result	✓ Passed
Advice Side loading door guides missing	
Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

CarCheck.co.uk page 3/12



MOT #7

Advice

required is 1.0mm (5.2.3 (e))

YP13UWX

report date: 2024-03-28

2019-06-14 16:18

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Steering box slight play between sector shaft and the drop arm (2.1.3 (a) (ii))

Fail Offside Rear Outline marker lamp missing (4.2.1 (a))

Fail Offside Rear Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Side loading door guides missing

Fail Nearside Rear Inner Tyre tread pattern not visible over the whole tread area when minimum depth

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Nearside Rear Outline marker lamp missing (4.2.1 (a))

MOT #6		2018-07-17 15:59
MOT test	number	795432446453
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Tyre worn close to legal limit/worn on edge BOTH INNERS (5.2.3 (e))	
Advice	Rear Tyre worn close to legal limit/worn on edge BOTH OUTERS (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Body has damage.	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2018-07-17 11:11

MOT test number 163214046360

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Body has damage.

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Tyre worn close to legal limit/worn on edge BOTH INNERS (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick BOTH SIDES (1.1.13 (a) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge BOTH OUTERS (5.2.3 (e))

MOT #4 2017-07-06 13:40

MOT test number 458415473948

Result ✓ Passed

MOT #3 2016-06-24 12:43

MOT test number 759623230234

Result
✓ Passed

MOT #2 2015-07-14 12:32

MOT test number 709935295166

Result ✓ Passed

MOT #1 2014-06-30 12:38

MOT test number 446781784175

Result

Passed

Notice N/s/r inner tyre 2mm depth

Notice O/s side marker lamp not working

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Days left 307

MOT expiry date 7 March 2025

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	history

o mile motory	
For how long did the current and previous owner(s) have this FORD? How many owner Check it in the premium report and see all owner registrations. Download the full repo	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	AIN UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-07-08
Last registration	2024-03-08
Complete history	See info



Designation #1	2012 07 00	22 m;
Registration #1	2013-07-08	22 mi
Registration #2	2014-06-30	35.036 mi
Registration #3	2015-07-14	209.868 mi
Registration #4	2016-06-24	377.184 mi
Registration #5	2017-07-06	260.030 mi
Registration #6	2018-07-17	288.536 mi
Registration #7	2018-07-17	288.538 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 mi
Registration #12		0.77 44
Registration #13		0.07 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	DU74886

CarCheck.co.uk page 12/12