





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D2 SE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

		1
ᆮ	HLIV	-

Date	2021-02-06
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim	- 1				
Μ	()	1	าเ	ST	'n	rv

MOT expiry date	2025-03-31
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #10	2024-03-06 15:54
MOT test number	297752209593
Result	✓ Passed
Next expiry date	2025-03-31

MOT #9	2023-03-31 08:48
MOT test number	565656837612
Result	✓ Passed

MOT #8		2022-03-04 14:45
MOT test	number	221056410638
Result		✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-04-01 11:15
MOT test number	472525312434
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-03-23 14:05

MOT test number 843069729860

Result X Failed

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2020-10-02 15:59

MOT test number 906063543004

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2020-10-02 11:22

MOT test number 174536776895

Result × Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))

MOT #3 2019-09-24 16:16

MOT test number 508361160167

Result
✓ Passed

Advice Filler neck damp

Advice Nearside Rear Tyre cracked

MOT #2 2018-09-24 16:01

MOT test number 522331039792

Result

Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

 MOT #1
 2017-09-25 10:12

 MOT test number
 613567487548

Result ✓ Passed

CarCheck.co.uk page 5/12



PK64WUD report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

PK64WUD

report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info

Plate changes

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-08
Last registration	2024-03-06
Complete history	See info



Registration #1	2014-12-08	23 mi
Registration #2	2017-09-25	36.449 mi
Registration #3	2018-09-24	46.693 mi
Registration #4	2019-09-24	59.137 mi
Registration #5	2020-10-02	64.508 mi
Registration #6	2020-10-02	64.508 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		77.777 au

More info >

CarCheck.co.uk page 11/12



PK64WUD report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1438 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/:

Number of axles 2

Engine number 3047885