



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Silver
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-01
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	38
Total items failed	8

MOT #17 2023-08-19 10:17

MOT test number 217909400024

Result ✓ Passed

Next expiry date 2024-09-01

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Door mirror temporary repaired with stuck on glass
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #16 2022-08-31 10:40

MOT test number 932184773899

Result ✓ Passed

- Advice** Central Front Exhaust mounting defective corroded (6.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material fixing corroded (1.1.11 (c))
- Advice** Under tray fitted obscuring items from view
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer side wall but not excessive (5.2.3 (d) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material pipe fixing corroded (1.1.11 (c))

**MOT #15** 2021-09-02 10:53**MOT test number** 307800048639**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14** 2020-03-09 16:40**MOT test number** 333516217131**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2020-02-28 11:03**MOT test number** 486908931336**Result** ✗ Failed**MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #12** 2019-03-28 08:28**MOT test number** 995786192473**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened corroded on inner surface (1.1.14 (a) (ii))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view stonechip (3.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

**MOT #11** 2018-04-06 07:49**MOT test number** 906242791448**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement front bush (2.4.G.2)

MOT #10 2018-04-06 07:49**MOT test number** 644937679964**Result** ✗ Failed

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement front bush (2.4.G.2)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

MOT #9 2017-04-04 11:23**MOT test number** 718982486849**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit at limit 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit at limit 1.6mm (4.1.E.1)

MOT #8 2017-04-04 07:59**MOT test number** 759470985228**Result** ✗ Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Tyre worn close to the legal limit at limit 1.6mm (4.1.E.1)

Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit at limit 1.6mm (4.1.E.1)

Fail Nearside Rear wheel bearing rough when rotated (2.6.1)

**MOT #7** 2016-03-18 11:51**MOT test number** 133061353441**Result** ✓ Passed**MOT #6** 2015-03-30 15:58**MOT test number** 398089185063**Result** ✓ Passed**MOT #5** 2015-03-30 10:24**MOT test number** 559889985071**Result** ✗ Failed**Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)**MOT #4** 2014-03-22 12:18**MOT test number** 116551584000**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2014-03-22 12:18**MOT test number** 197771184010**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)



MOT #2	2013-04-02 14:40
MOT test number	499812993024
Result	✓ Passed
Notice	Both front tyres cracking/splitting
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2012-03-15 14:45
MOT test number	749735472062
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-28
Current registration	*****
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-04-14
Last registration	2023-08-19
Complete history	See info



Registration #1	2009-04-14	21 mi
Registration #2	2012-03-15	31.709 mi
Registration #3	2013-04-02	45.045 mi
Registration #4	2014-03-22	65.259 mi
Registration #5	2015-03-30	84.770 mi
Registration #6	2015-03-30	84.770 mi
Registration #7	2016-03-18	107.470 mi
Registration #8	2017-04-04	132.524 mi
Registration #9	2017-04-04	132.524 mi
Registration #10	2018-04-04	152.524 mi
Registration #11	2018-04-04	152.524 mi
Registration #12	2018-04-04	152.524 mi
Registration #13	2018-04-04	152.524 mi
Registration #14	2018-04-04	152.524 mi
Registration #15	2018-04-04	152.524 mi
Registration #16	2018-04-04	152.524 mi
Registration #17	2018-04-04	152.524 mi
Registration #18	2018-04-04	152.524 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	613349
---------------	--------