





report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 DRIVE ES
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-03

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-05
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	5
Total items failed	3

MOT #11	2023-06-29 11:00
MOT test number	318614056899
Result	✓ Passed
Next expiry date	2024-07-05

MOT #10	2022-07-06 09:28
MOT test number	425449866219
Result	✓ Passed

MOT #9	2021-06-05 15:24
MOT test number	989755308590
Result	✓ Passed

MOI #8		2021-06-05 15:24
MOT test number		605112037876
Result		X Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/12



AK12NDN

report date: 2024-03-29

MOT #7		2020-06-29 08:18
MOT test	number	914136177140
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6		2019-06-19 08:08
MOT test number		363456219700
Result		✓ Passed
MOT #5		2018-06-28 10:18
MOT test number		886650952858
Result		✓ Passed
MOT #4		2017-03-24 15:34
MOT test number		920116031795
Result		✓ Passed
MOT #3		2017-03-24 15:34
MOT test number		943489379981
Result		★ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
100		
Pass with rectification	Offside Headlamp aim too low (1.8)	

MOT #2	2016-03-04 10:16
MOT test number	334691281214
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2015-03-24 12:25

MOT test number 716353085064

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



AK12NDN

report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-30
Last registration	2023-06-29
Complete history	See info



Registration #1	2012-03-30	7 mi
Registration #2	2015-03-24	42.729 mi
Registration #3	2016-03-04	52.915 mi
Registration #4	2017-03-24	70.893 mi
Registration #5	2017-03-24	70.893 mi
Registration #6	2018-06-28	76.060 mi
Registration #7	2019-06-19	83.753 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		10.000 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1756 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2
Engine number 1161516