




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Black
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-03
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	16
Total items failed	4

MOT #17	2023-06-01 10:21
MOT test number	439547753904
Result	✓ Passed
Next expiry date	2024-06-03

MOT #16	2023-06-01 10:21
MOT test number	459279739133
Result	✗ Failed
Pass with rectification Offside Headlamp aim too low (4.1.2 (a))	

MOT #15	2022-06-03 12:45
MOT test number	204762050323
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perishing. 2016. (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Wearing low on the inner edge. (5.2.3 (e))	
Advice Nearside Rear Lower Exhaust silencer corroded.	

**MOT #14** 2022-05-31 14:10**MOT test number** 151572150308**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perishing. 2016. (5.2.3 (d) (ii))**Advice** Nearside Rear Lower Exhaust silencer corroded.**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing low on the inner edge. (5.2.3 (e))**MOT #13** 2021-06-04 09:35**MOT test number** 650264033193**Result** ✓ Passed**MOT #12** 2021-06-03 05:37**MOT test number** 556714397988**Result** ✗ Failed**Fail** Offside Front Inner Tyre has ply or cords exposed 195/55 R15 (5.2.3 (d) (ii))**MOT #11** 2020-06-03 13:05**MOT test number** 463459707205**Result** ✓ Passed**Advice** Offside Rear wheel / brake has restricted free movement**Advice** Offside Front Tyre worn close to legal limit/worn on edge heavily worn on inner edge / devoid of tread / advise replacement / 195/55/R15 (5.2.3 (e))

**MOT #10** 2020-06-03 09:56**MOT test number** 809737548423**Result** ✗ Failed**Advice** Offside Rear wheel / brake has restricted free movement**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge heavily worn on inner edge / devoid of tread / advise replacement / 195/55/R15 (5.2.3 (e))**MOT #9** 2019-04-08 15:09**MOT test number** 681875013119**Result** ✓ Passed**MOT #8** 2018-03-23 12:39**MOT test number** 319376458132**Result** ✓ Passed**MOT #7** 2017-03-31 08:22**MOT test number** 300387215559**Result** ✓ Passed**MOT #6** 2016-04-08 08:38**MOT test number** 821018303031**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2015-04-10 10:34**MOT test number** 296950605442**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2014-04-10 09:23**MOT test number** 285700604406**Result** ✓ Passed**MOT #3** 2013-04-04 09:34**MOT test number** 568704093091**Result** ✓ Passed**MOT #2** 2012-04-12 10:29**MOT test number** 658623502168**Result** ✓ Passed**MOT #1** 2011-04-14 16:22**MOT test number** 408844301181**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
3 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	3 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GK58SGY
Plate since	2019-06-29
Current registration	 GK58SGY
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-02
Last registration	2023-06-01
Complete history	See info



Registration #1	2008-09-02	6 mi
Registration #2	2011-04-14	3.949 mi
Registration #3	2012-04-12	11.767 mi
Registration #4	2013-04-04	18.617 mi
Registration #5	2014-04-10	25.641 mi
Registration #6	2015-04-10	32.435 mi
Registration #7	2016-04-08	38.958 mi
Registration #8	2017-03-31	45.965 mi
Registration #9	2018-03-23	53.955 mi
Registration #10	2019-04-08	62.582 mi
Registration #11	2020-05-20	71.277 mi
Registration #12	2021-05-20	80.277 mi
Registration #13	2022-05-20	89.277 mi
Registration #14	2023-05-20	98.277 mi
Registration #15	2024-05-20	107.277 mi
Registration #16	2025-05-20	116.277 mi
Registration #17	2026-05-20	125.277 mi
Registration #18	2027-05-20	134.277 mi
Registration #19	2028-05-20	143.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD524379