





### General information

| Make                | ΤΟΥΟΤΑ             |
|---------------------|--------------------|
| Model               | LAND CRUISER VX TD |
| Colour              | Blue               |
| Year of manufacture | 2002               |
| Top speed           | 105 mph            |
| 0 - 60 mph          | 13.6 seconds       |
| Gearbox             | 4 speed automatic  |

### Engine & fuel consumption

| Power                   | 201 BHP             |
|-------------------------|---------------------|
| Max. torque             | 430 Nm at 1.400 rpm |
| Engine capacity         | 4.164 cc            |
| Cylinders               | 6                   |
| Fuel type               | Diesel              |
| Consumption city        | 17.9 mpg            |
| Consumption extra urban | 26.2 mpg            |
| Consumption combined    | 22.4 mpg            |
| CO2 emission            | 340 g/km            |
| CO2 label               | Μ                   |







RF

 VS

VIEV

5 S

### Internet history

| Entry | 1 |
|-------|---|
| Date  |   |

Pictures

2021-02-05

10

Listing price

View report



source: autoonline.co.uk



# MOT history

| MOT expiry date    | 2025-02-12 |
|--------------------|------------|
| MOT pass rate      | 90 %       |
| MOT passed         | 18         |
| Failed MOT tests   | 2          |
| Total advice items | 27         |
| Total items failed | 5          |

| MOT #20   | 2024-02-13 10:44       |
|---|------------------------|
| MOT test number   | 406654386644           |
| Result  | 🗸 Passed               |
| Next expiry date  | 2025-02-12             |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light so | ources (4.7.1 (b) (i)) |
| Advice Sills chassis wheel arches corroding   |                        |
| Advice Brake fluid low  |                        |

| MOT #19                       | 2023-02-03 11:19 |
|-------------------------------|------------------|
| MOT test number               | 623672860185     |
| Result                        | ✓ Passed         |
| Advice Rear springs corroding |                  |

| MOT #18   | 2023-01-24 11:20 |
|---|------------------|
| MOT test number   | 320056725471     |
| Result  | 🗙 Failed         |
| Advice Rear springs corroding   |                  |
| <b>Fail</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))   |                  |
| <b>Fail</b> Parking brake efficiency below requirements (1.4.2 (a) (i)) |                  |
| Fail Offside Front Service brake grabbing severely (1.2.1 (c))          |                  |





| MOT #17         | 2022-01-11 10:15 |
|-----------------|------------------|
| MOT test number | 907893928450     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #16         | 2020-08-25 14:25 |
| MOT test number | 357094791872     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #15  | 2019-07-18 14:46 |
|--|------------------|
| MOT test number  | 478687647241     |
| Result   | ✓ Passed         |
| Advice Both front tyres wearing on the edges             |                  |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #14         | 2018-07-31 07:38 |
|-----------------|------------------|
| MOT test number | 600426479305     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #13         | 2017-08-03 08:52 |

| MOT test number  | 667949996483 |
|--|--------------|
| Result   | ✓ Passed     |
| Advice Rear anti roll bar d bushes worn with slight play |              |





| MOT #12  |  | 2016-08-08 07:39 |
|----------|--|------------------|
| MOT test | number   | 527151105531     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Front cv boot in poor condition                 |                  |
| Advice   | Offside Front cv boot in poor condition                  |                  |
| Advice   | Nearside Front anti roll bar link worn with play         |                  |
| Advice   | Offside Front anti roll bar link in poor conditon        |                  |
| Advice   | Offside Front bottom ball joint jacket in poor condition |                  |

| MOT #11         | 2015-08-11 08:55 |
|-----------------|------------------|
| MOT test number | 638617014044     |
| Result          | ✓ Passed         |

#### MOT #10

| MOT #10  |  | 2014-05-07 09:20 |
|----------|--|------------------|
| MOT test | number   | 875577824137     |
| Result   |  | ✓ Passed         |
| Notice   | N/s/f shock damp                               |                  |
| Notice   | O/s bottom ball joint jacket in poor condition |                  |
| Notice   | Handbrake effort just meet limits              |                  |
| Notice   | N/s/f wheel bearing has slight play            |                  |
| Notice   | O/s track rod end jacket in poor condition     |                  |





| MOT #9                  |   | 2013-04-17 08:41 |
|-------------------------|---|------------------|
| MOT test                | number  | 598277703114     |
| Result                  |   | ✓ Passed         |
| Advice                  | Offside Front Front wheel bearing has slight play (2.5.A.3c)                    |                  |
| <b>Advice</b> (2.4.G.2) | Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in exce  | essive movement  |
| Advice                  | Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)               |                  |
| <b>Advice</b> (2.4.G.2) | Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excess | sive movement    |

| MOT #8   | 2012-0  | )5-10 08:46 |
|----------|---|-------------|
| MOT test | number 939  | 241832102   |
| Result   |   | ✓ Passed    |
| Advice   | Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)  |             |
| Notice   | Both front tyres worn on the edges  |             |
| Advice   | Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |             |

| MOT #7   |                                | 2011-05-11 16:05 |
|----------|--------------------------------|------------------|
| MOT test | number                         | 215361531162     |
| Result   |                                | ✓ Passed         |
| Notice   | Front tyres wearing on egde    |                  |
| Notice   | Both wheel bearing slight play |                  |

| MOT #6          | 2010-05-10 10:36 |
|-----------------|------------------|
| MOT test number | 903840730109     |
| Result          | ✓ Passed         |
| MOT #5          | 2009-05-12 13:28 |
| MOT test number | 714572039154     |

Result





| MOT #4   | 2008-05-14 15:14 |
|--|------------------|
| MOT test number  | 614485738183     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #3   | 2008-05-09 16:54 |
| MOT test number  | 840770038186     |
| Result   | 🗙 Failed         |
| Fail Offside Outer Front constant velocity joint gaiter split (2.5.C.1a) |                  |
| Fail Offside Steering rack gaiter split (2.2.D.2d)                       |                  |
|  |                  |
| MOT #2   | 2007-05-08 09:54 |
| MOT test number  | 633208427191     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #1   | 2005-11-16 16:55 |
| MOT test number  | 374610725344     |
| Result   | ✓ Passed         |



Tax & MOT check

| Taxed<br>Tax due:<br>1 February 2025 | ✓<br>MOT<br>Expires:<br>12 February 2025 |
|--------------------------------------|--|
| Tax status                           | Valid until 1 February                   |
| Days left                            | 277                                      |
| MOT expiry date                      | 12 February 2025                         |
| Full MOT history                     | See MOT history                          |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | К          |
| Single payment (12 months)              | £ 395,00,- |
| Single six month payment                | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |                                       |
|----------|---------------------------------------|
| Date     |                                       |
| Category | <br>Lamp                              |
| Туре     | K K K K K K K K K K K K K K K K K K K |
| Damage 2 | AMPLE                                 |
| Damage 2 |                                       |
| Date     | <br>*                                 |
| Category | <br>amer                              |
| Туре     |                                       |

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.700 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******  |             |
|---|-------------|
| ***********   |             |
| *******   |             |
| ******  |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this TOYOTA had different number plates. |             |
| Number of plates  | ,           |
| Carrent registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   | More info > |





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 22         |
| First mileage registration | 2002-10-24 |
| Last registration          | 2024-02-13 |
| Complete history           | See info   |



| Registration #1  | 2002-10-24 | 27 mi      |
|------------------|------------|------------|
| Registration #2  | 2005-11-16 | 52.269 mi  |
| Registration #3  | 2007-05-08 | 77.484 mi  |
| Registration #4  | 2008-05-09 | 90.804 mi  |
| Registration #5  | 2008-05-14 | 90.887 mi  |
| Registration #6  | 2009-05-12 | 98.459 mi  |
| Registration #7  | 2010-05-10 | 107.114 mi |
| Registration #8  | 2011-05-11 | 112.319 mi |
| Registration #9  | 2012-05-10 | 115.415 mi |
| Registration #10 | 2013-04-17 | 119.259 mi |
| Registration #11 | 2014-05-07 | 121.493 mi |
| Registration #12 |            | 11.777 est |
| Registration #13 |            | 11.777 est |
| Registration #14 |            | 11.777 est |
| Registration #15 |            | 11.707 esi |
| Registration #16 |            | 11.777 est |
| Registration #17 |            | 11.707 esi |
| Registration #18 |            | 11.777 est |
| Registration #19 |            | 11.707 esi |
| Registration #20 |            | 11.777 est |
| Registration #21 |            | 11.777 mi  |
| Registration #22 |            | 11.777 est |
|                  |            |            |





### Car features

| S0225  | Air conditionin |
|--------|-----------------|
| \$0295 |                 |
| S0482  |                 |
| \$0501 |                 |
| \$0566 |                 |
| \$0567 |                 |
| S0569  |                 |

## Dimensions & weight

| Width      | 1940 mm |
|------------|---------|
| Height     | 1890 mm |
| Length     | 4890 mm |
| Wheel base | 2850 mm |

## Additional information

| Fuel tank capacity | 96               |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of axles    | 2                |
| Engine number      | 1HD0226721       |