





General information

Make	NISSAN
Model	PRIMASTAR DCI SE SHR P/V
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP	0 < 101 A
Engine capacity	1.995 cc	101 - 120 B
Cylinders	4	121 - 140 E
uel type	Diesel	141 - 165 F G
		166 - 185

225+



MOT history

MOT expiry date	2025-04-08
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	32
Total items failed	43

MOT #20	2024-04-09 14:06
MOT test number	641040237645
Result	🗸 Passed
Next expiry date	2025-04-08
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (.c))

МОТ #19	2024-04-08 13:36
MOT test number	219189208662
Result	🗙 Failed
Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	ingress of dirt
Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Fail Nearside Windscreen washer not working (3.5 (a))	
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Fail Offside Rear Brake pipe excessively corroded front to back brake pipe (1.1.11 (c))	





MOT #18	2023-04-05 15:52
MOT test number	328197668820
Result	✓ Passed
 Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting bush (5.3.4 (a) (i)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) 	g in excessive movement 'D'
MOT #17	2023-04-05 08:05
MOT test number	530006874720
Result	🗙 Failed
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting bush (5.3.4 (a) (i))	g in excessive movement 'D'
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #16		2022-04-05 11:42
MOT test	number	580249933045
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



BN10WVJ report date: 2024-03-28

MOT #15		2022-04-05 11:42
MOT test number		727935049884
Result		🗙 Failed
Advice Nearside Rear B	rake pad(s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice Offside Rear Bra	ke pipe corroded, covered in grease or other material (1.1.1	.1 (c))
Advice Offside Rear Bra	ke pad(s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification (4.7.1 (b) (ii))	Registration plate lamp inoperative in the case of a single	lamp or all lamps
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	

MOT #14	2021-04-09 10:43
MOT test number	546052712299
Result	✓ Passed

MOT #13	2020-09-02 08:14
MOT test number	684173841541
Result	✓ Passed

MOT #12	2020-08-28 08:12
MOT test number	901498525230
Result	🗙 Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	





МОТ #	11	2019-08-02 16:17
MOT to	est number	718686981457
Result		✓ Passed
Advi	ce Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	:))
MOT #	-10	2019-08-02 08:45
MOT to	est number	404624915601
Result		🗙 Failed
Fail	Offside Front Brake hose bulging under pressure (1.1.12 (d))	
Advi	ce Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	:))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Nearside Front Brake hose bulging under pressure (1.1.12 (d))	
Advi	ce Park brake cables corroded	
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Nearside Rear Brake linkage has restricted free movement Brake caliper (1.1.15 (e))
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	
Fail nearsi	Electrical wiring insulation so damaged or deteriorated it is likely to cause a short-ci de engine bay (4.11 (c) (ii))	rcuit To Solenoid
Advi	ce Rear Brake discs corroded	

MOT #9		2018-08-07 13:40
MOT test	number	784829356509
Result		✓ Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #8	2018-08-07 08:19
MOT test number	286638873353
Result	🗙 Failed
Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2017-09-01 09:35
MOT test number	886910671301
Result	✓ Passed

МОТ #6	2016-07-30 09:41
MOT test number	818148499918
Result	✓ Passed

MOT #5	2016-07-30 08:03
MOT test number	543166653076
Result	🗙 Failed
Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)	
Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no logingress of dirt etc (2.5.C.1a)	nger prevents the
Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)	
Fail Offside Front constant velocity joint gaiter insecure to the extent that it no long ingress of dirt etc (2.5.C.1a)	ger prevents the
Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)	



MOT #4	2015-08-07 09:10
MOT test number	358259215237
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #3	2014-08-06 14:25
MOT test number	918588614233
Result	✓ Passed
MOT #2	2013-05-03 17:41
MOT test number	319893723104
Result	✓ Passed

Notice	Metal particles in both rear tyres
Notice	Oil leak
Notice	Spare wheel missing

BN10WVJ

report date: 2024-03-28





MOT #1	2013-05-01 17:36
MOT test number	299901823452
Result	🗙 Failed
Fail Offside Front Brake pipe fouled by moving parts (3.6.B.2a)	
Notice Oil leak	
FailNearside Front position lamp(s) not working (1.1.A.3b)	
Fail Offside Front Brake pipe excessively damaged (3.6.B.2c)	
Notice Spare wheel missing	
Fail Nearside Headlamp aim not tested (1.8.A.1c)	
Fail Offside Front Electrical wiring insecure (1.9.2a)	
Fail Offside Front Brake pipe inadequately clipped (3.6.B.1)	
Notice Nail in offside rear tyre	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Nearside Front Brake pipe excessively damaged (3.6.B.2c)	
Notice Metal particles in both rear tyres	
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
Fail Offside Headlamp aim too high (1.8)	
Fail Nearside Front Brake pipe inadequately clipped (3.6.B.1)	



BN10WVJ report date: 2024-03-28

Tax & MOT check







Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

annesses.	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-04-07
Last registration	2024-04-09
Complete history	<u>See info</u>



Registration #2 2013-05-01 86.558 m Registration #3 2013-05-03 86.558 m Registration #4 2014-08-06 97.743 m Registration #5 2015-08-07 102.687 m Registration #6 2016-07-30 107.072 m Registration #7 2016-07-30 107.072 m Registration #8 2017-09-01 112.981 m Registration #9 2018-08-07 119.741 m Registration #10 2018-08-07 119.794 m			
Registration #3 2013-05-03 86.558 m Registration #4 2014-08-06 97.743 m Registration #5 2015-08-07 102.687 m Registration #6 2016-07-30 107.072 m Registration #6 2016-07-30 107.072 m Registration #7 2016-07-30 112.981 m Registration #10 2018-08-07 119.794 m Registration #11 2019-08-02 128.344 m Registration #12 Its and the second the	Registration #1	2010-04-07	27 mi
Registration #4 2014-08-06 97.743 m Registration #5 2015-08-07 102.687 m Registration #6 2016-07-30 107.072 m Registration #7 2016-07-30 107.072 m Registration #8 2017-09-01 112.981 m Registration #8 2018-08-07 119.741 m Registration #10 2018-08-07 119.741 m Registration #11 2019-08-02 128.344 m Registration #12 Item Provide P	Registration #2	2013-05-01	86.558 mi
Registration #5 2015-08-07 102.687 m Registration #6 2016-07-30 107.072 m Registration #7 2016-07-30 107.072 m Registration #8 2017-09-01 112.981 m Registration #9 2018-08-07 119.741 m Registration #10 2019-08-02 128.344 m Registration #12 128.344 m Registration #13 128.344 m Registration #14 110 Registration #15 110 Registration #16 110 Registration #17 110 Registration #18 110 Registration #18 110 Registration #19 110 Registration #20 110	Registration #3	2013-05-03	86.558 mi
Registration #6 2016-07-30 107.072 m Registration #7 2016-07-30 107.072 m Registration #8 2017-09-01 112.981 m Registration #9 2018-08-07 119.741 m Registration #10 2018-08-07 119.744 m Registration #10 2019-08-02 128.344 m Registration #12 Image: Comparison of the state of th	Registration #4	2014-08-06	97.743 mi
Registration #7 2016-07-30 107.072 m Registration #8 2017-09-01 112.981 m Registration #9 2018-08-07 119.741 m Registration #10 2018-08-07 119.794 m Registration #11 2019-08-02 128.344 m Registration #12 Image: Comparison of the state of	Registration #5	2015-08-07	102.687 mi
Registration #8 2017-09-01 112.981 m Registration #9 2018-08-07 119.741 m Registration #10 2018-08-07 119.794 m Registration #11 2019-08-02 128.344 m Registration #12 112.981 m 110.794 m Registration #13 2019-08-02 128.344 m Registration #14 110.794 m 110.794 m Registration #15 110.794 m 110.794 m Registration #16 110.794 m 110.794 m Registration #17 110.794 m 110.794 m Registration #18 110.794 m 110.794 m Registration #19 110.794 m 110.794 m Registration #20 110.794 m 110.794 m	Registration #6	2016-07-30	107.072 mi
Registration #9 2018-08-07 119.741 m Registration #10 2018-08-07 119.794 m Registration #11 2019-08-02 128.344 m Registration #12 Image: Comparison of the state of the st	Registration #7	2016-07-30	107.072 mi
Registration #102018-08-07119.794 mRegistration #112019-08-02128.344 mRegistration #12	Registration #8	2017-09-01	112.981 mi
Registration #112019-08-02128.344 mRegistration #122019-08-02128.344 mRegistration #13Registration #13128.344 mRegistration #13Registration #13128.344 mRegistration #14Registration #14128.344 mRegistration #15Registration #15128.344 mRegistration #16Registration #16128.344 mRegistration #17Registration #18128.344 mRegistration #18128.344 m128.344 mRegistration #19128.344 m128.344 mRegistration #20128.344 m128.344 m	Registration #9	2018-08-07	119.741 mi
Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #10	2018-08-07	119.794 mi
Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #11	2019-08-02	128.344 mi
Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #12		11.777 est
Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #13		11.777 esi
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	Registration #14		11.777 est
Registration #17 Registration #18 Registration #19 Registration #20	Registration #15		11.777 esi
Registration #18 Registration #19 Registration #20	Registration #16		11.777 est
Registration #19 Registration #20	Registration #17		11.777 esi
Registration #20	Registration #18		11.777 est
	Registration #19		11.777 esi
Registration #21	Registration #20		11.777 est
	Registration #21		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Additional informationFuel deliveryDirect InjectionNumber of doors4Number of seats3Engine number072560