





### General information

Make	ΤΟΥΟΤΑ
Model	IQ VVT-I FIRE AC
Colour	White
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







## Internet history

Entry 1
Date
Pictures


2021-06-16

3

Listing price

View report







source: autotrader.co.uk



### MOT history

MOT expiry date	2025-04-07
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	19
Total items failed	4

MOT #10	2024-04-08 14:05
MOT test number	846542365768
Result	✓ Passed
Next expiry date	2025-04-07
<b>Minor</b> Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #9	2024-04-05 15:34
MOT test number	706149082906
Result	🗙 Failed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps (4.7.1 (b) (i))	or light sources
<b>Fail</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))	
<b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Front Windscreen washer not working (3.5 (a))	
<b>Fail</b> Electronic stability control warning lamp indicates a fault (7.12 (e))	

МОТ #8	2023-01-03 15:43
MOT test number	825375332806
Result	✓ Passed





MOT #7	2022-01-03 11:34
MOT test number	800908406128
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2	mm (5.2.3 (e))
MOT #6	2021-01-05 09:15
MOT test number	826303071781
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weat (ii))	akened Nearside + Offside (1.1.14 (a)
Minor Front Windscreen wiper blade defective Both (3.4 (b) (i))	
Advice Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Central Heatshield loose but is unlikely to become detached	
Minor Offside Front Anti-roll bar linkage ball joint dust cover severel	y deteriorated (5.3.4 (b) (i))
Advice Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #5		2019-05-15 13:36
MOT test	number	515907978669
Result		✓ Passed
Advice	Rear brake discs slightly corroded	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm cracked trea	ad (5.2.3 (e))
Advice	Front brake discs slightly corroded on the inner faces	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm perished (5.2	.3 (e))





MOT #4		2017-11-18 09:36
MOT test i	number	373903220351
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit Low on inside edge and perished	in tread (4.1.E.1)
MOT #3		2016-12-09 15:50
MOT test I	number	354547732448
Result		✓ Passed
Advice	Nearside Rear Brake hose has slight corrosion to ferrules to axle (3.6.B.4e)	
Advice	Nearside Rear Brake hose has slight corrosion to ferrules to caliper (3.6.B.4e)	
Advice	Offside Rear Brake hose has slight corrosion to ferrules to axle (3.6.B.4e)	
Advice	Offside Rear Brake hose has slight corrosion to ferrules to caliper (3.6.B.4e)	

MOT #2	2015-12-10 13:01
MOT test number	847030842244
Result	✓ Passed
MOT #1	

MOT #1	2014-12-15 17:25
MOT test number	146109444306
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due:	√ MOT Expires:
1 September 2024	Expires: 7 April 2025
Tax status	Valid until 1 September
Days left	126
MOT expiry date	7 April 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEMP
Туре	
Damage 2	AMPL
Damaye 2	E CAT ON
Date	14 N
Category	AMP
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	
**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-03-13
Last registration	2024-04-08
Complete history	See info



Registration #1	2012-03-13	21 mi
Registration #2	2014-12-15	33.043 mi
Registration #3	2015-12-10	34.419 mi
Registration #4	2016-12-09	35.864 mi
Registration #5	2017-11-18	37.223 mi
Registration #6	2019-05-15	49.115 mi
Registration #7		11.777 mi
Registration #7 Registration #8		10.000 est
		01,000 est 01,000 est 01,000 est
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est
Registration #8 Registration #9		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1615 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	830 kg
Max. allowed weight	1190 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12