





report date: 2024-03-29

General information

Make	MINI
Model	COOPER S
Colour	Black
Year of manufacture	2013
Top speed	142 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

Date 2022-11-30


Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-06-06

Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-03

Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-12-06
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #11	2023-11-28 08:23
MOT test number	867754853528
Result	✓ Passed
Next expiry date	2024-12-06
Minor Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning	(4.3.1 (a) (i))

MOT #10	2022-12-07 17:21
MOT test number	931092507189
Result	✓ Passed

MOT #9	2022-12-05 16:43
MOT test number	610351087913
Result	X Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Minor Offside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))	

MOT #8	2022-06-01 14:22
MOT test number	587292252473
Result	✓ Passed

CarCheck.co.uk page 3/12



Advice

GU63BXP

report date: 2024-03-29

MOT #7	2022-05-31 16:50
MOT test number	783731834493
Result	× Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Advice Offside Rear Nail in tyre	
Advice Offside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Rear number plate lights poor light output	

Advice Rear number plate lights poor light output	
MOT #6	2021-06-03 06:08
MOT test number	497602146238
Result	✓ Passed
MOT #5	2020-10-02 12:03
MOT test number	241053541337
Result	✓ Passed
MOT #4	2019-09-19 09:27
MOT test number	506305664762
Result	✓ Passed
MOT #3	2018-09-11 15:45
MOT test number	632853947595
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



report date: 2024-03-29

MOT #2

MOT test number

Passed

Advice Nearside Rear tyre has minor damage to inner side wall

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit Wearing on inner edge (4.1.E.1)

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Offside Front Tyre worn close to the legal limit Wearing on inner edge (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK AIR
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-05
Last registration	2023-11-28
Complete history	See info



Registration #1	2013-10-05	28 mi
Registration #2	2016-09-28	12.096 mi
Registration #3	2017-09-22	16.175 mi
Registration #4	2018-09-11	20.967 mi
Registration #5	2019-09-19	24.756 mi
Registration #6	2020-10-02	27.715 mi
Registration #7	2021-06-03	29.017 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles2Engine numberA767J575