





report date: 2024-03-29

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT TDV6 HSE
Colour	Black
Year of manufacture	2007
Top speed	120 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	188 BHP
1 01101	100 5111
Max. torque	440 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	34.4 mpg
Consumption combined	27.7 mpg
CO2 emission	265 g/km
CO2 label	М



CarCheck.co.uk page 1/13




Internet history

Entry 2

Date 2023-02-02

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-10
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	36
Total items failed	10

MOT #10	2023-08-11 09:08
MOT test number	588566378217
Result	✓ Passed
Next expiry date	2024-08-10

МС	OT #9	2023-08-08 13:34

MOT test number 457145562032

Result

X Failed

Fail Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

MOT #8	2	023-01-24	14:13
1.10 1 // 0			

MOT test	number 3898	53597865
Result		✓ Passed
Advice	Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Lower Suspension arm corroded but not seriously weakened n/s o/s (5.3.3 (b) (i))	
Advice	Rear Lower Suspension arm corroded but not seriously weakened n/s o/s (5.3.3 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Minor	Offside Rear Upper Brake pipe inadequately clipped or supported (1.1.11 (d) (i))	

CarCheck.co.uk page 3/13



MOT #7 2023-01-11 10:33

MOT test number 481120693219

Result X Failed

Fail Offside Front Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Rear Lower Suspension arm corroded but not seriously weakened n/s o/s (5.3.3 (b) (i))

Minor Offside Rear Upper Brake pipe inadequately clipped or supported (1.1.11 (d) (i))

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

Advice Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #6 2021-11-17 11:50

MOT test number 389649825257

Result \(\sqrt{Passed} \)

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Under-body surface corrosion

CarCheck.co.uk page 4/13



MOT #5 2021-11-17 11:50

MOT test number 837618989885

Result X Failed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Under-body surface corrosion

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #4 2020-11-19 15:15

MOT test number 647293005635

MOT #3 2019-05-24 12:52

MOT test number 533983500420

Result
✓ Passed

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both side steps corroded

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Offside Front suspension pipe work corroded

CarCheck.co.uk page 5/13



MOT #2 2018-05-23 13:55

MOT test number 595916161533

Result ✓ Passed

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement just passes (5.3.4 (a) (i))

Advice Suspension pipes at offside front chassis rail corroded

Advice Fluid leak, but not excessive gearbox (8.4.1 (a) (i))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both steps corroded

Minor

Central Upper Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

MOT #1 2018-05-22 16:05

MOT test number 168070054528

Result X Failed

Advice Suspension pipes at offside front chassis rail corroded

Fail Offside Rear Tyre has ply or cords exposed on inside shoulder (5.2.3 (d) (ii))

Minor Central Upper Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement just passes (5.3.4 (a) (i))

Advice Both steps corroded

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Fluid leak, but not excessive gearbox (8.4.1 (a) (i))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITEL	HISLULY

e when mistery	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-03-09
Last registration	2023-08-11
Complete history	See info



Registration #1	2007-03-09	8 mi
Registration #2	2018-05-22	107.559 mi
Registration #3	2018-05-23	107.563 mi
Registration #4	2019-05-24	114.258 mi
Registration #5	2020-11-19	124.002 mi
Registration #6		11.777 es
Registration #7	2021-11-17	126.477 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		77,777 44
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.707 au

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1928 mm
Height	1784 mm
Length	4788 mm
Wheel base	2745 mm
Kerb weight	2455 kg
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	84 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0169131276DT

CarCheck.co.uk page 13/13