



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Black
Year of manufacture	2007
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	138 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-08-08
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-21
Pictures	32
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-04
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	46
Total items failed	20

MOT #19	2023-09-19 09:10
MOT test number	485527437786
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #18**

2023-09-18 10:58

MOT test number

464982114285

Result

✗ Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Emissions unable to be completed (8.2.1.2 (d))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #17**

2022-10-03 13:55

MOT test number

646048863030

Result

✓ Passed

Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**MOT #16**

2021-10-01 11:49

MOT test number

183959172623

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

**MOT #15** 2020-10-05 14:42**MOT test number** 532868307123**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Advice** Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14** 2020-09-26 11:15**MOT test number** 141456178863**Result** ✗ Failed**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle in and outside cant open (6.2.3 (a))**Advice** Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle in and outside cant open (6.2.3 (a))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2019-09-19 11:05**MOT test number** 712902255272**Result** ✓ Passed

**MOT #12**

2019-09-18 12:55

MOT test number

724809122485

Result

✗ Failed

- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11

2018-09-28 11:37

MOT test number

131681036744

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear lens cracked

MOT #10

2017-12-19 14:42

MOT test number

785003100390

Result

✓ Passed

- Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Front tyre wearing on inside edge
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front tyre has cracks between tread and sidewall

**MOT #9** 2017-11-22 09:32**MOT test number** 743520081279**Result** ✗ Failed

- Advice** Front Registration plate damaged
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front tyre wearing on inside edge
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Nearside Front tyre has cracks between tread and sidewall
- Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #8 2016-08-25 15:51**MOT test number** 122492443025**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Registration Plate damaged
- Advice** Offside Rear Tyre worn close to the legal limit and worn on outside edge (4.1.E.1)

MOT #7 2015-08-22 09:03**MOT test number** 453161720991**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases FLEXIBLE (7.1.2)

**MOT #6** 2014-09-01 11:53**MOT test number** 578514344265**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #5** 2014-08-28 15:50**MOT test number** 338620244226**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm synthetic bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Front Lower Suspension arm synthetic bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-08-06 11:26**MOT test number** 489788113212**Result** ✓ Passed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** O/s/front tyre wearing on inner and outer edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-10-05 16:05**MOT test number** 327058171433**Result** ✓ Passed



MOT #2	2010-09-30 15:18
MOT test number	751673470246
Result	✓ Passed

MOT #1	2010-09-30 09:23
MOT test number	344373770442
Result	✗ Failed
<div>Fail</div> Offside Side repeater not working (1.4.A.2c)	



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CK57KUN
Plate since	2019-06-29
Current registration	 CK57KUN
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-10-04
Last registration	2023-09-19
Complete history	See info



Registration #1	2007-10-04	15 mi
Registration #2	2010-09-30	21.470 mi
Registration #3	2010-09-30	21.472 mi
Registration #4	2011-10-05	24.856 mi
Registration #5	2013-08-06	32.091 mi
Registration #6	2014-08-28	36.935 mi
Registration #7	2014-09-01	36.956 mi
Registration #8	2015-08-22	41.271 mi
Registration #9	2016-08-25	45.168 mi
Registration #10	2017-11-22	48.160 mi
Registration #11	2017-12-19	48.356 mi
Registration #12	2019-05-20	51.277 mi
Registration #13	2019-05-20	51.277 mi
Registration #14	2019-05-20	51.277 mi
Registration #15	2019-05-20	51.277 mi
Registration #16	2019-05-20	51.277 mi
Registration #17	2019-05-20	51.277 mi
Registration #18	2019-05-20	51.277 mi
Registration #19	2019-05-20	51.277 mi
Registration #20	2019-05-20	51.277 mi
Registration #21	2019-05-20	51.277 mi
Registration #22	2019-05-20	51.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531