



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 T5 R-DESIGN
Colour	Silver
Year of manufacture	2011
Top speed	146 mph
0 - 60 mph	6.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	227 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.9 mpg
Consumption extra urban	43.5 mpg
Consumption combined	31.4 mpg
CO2 emission	211 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-07-03
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-05
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #14	2023-07-18 09:19
MOT test number	273784086517
Result	✓ Passed
Next expiry date	2024-08-05
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-08-01 15:00
MOT test number	572685474598
Result	✓ Passed

MOT #12	2021-08-06 11:46
MOT test number	476220377419
Result	✓ Passed

MOT #11	2021-08-06 08:31
MOT test number	460940537190
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2020-07-25 08:36**MOT test number** 933084149717**Result** ✓ Passed**MOT #9** 2019-08-03 14:30**MOT test number** 763458732720**Result** ✓ Passed**MOT #8** 2019-05-01 14:12**MOT test number** 434498595128**Result** ✓ Passed**MOT #7** 2018-11-19 15:47**MOT test number** 250332622128**Result** ✓ Passed**Advice** Outer sill covers fitted**Advice** Under trays fitted**MOT #6** 2018-11-16 11:25**MOT test number** 839740441835**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid washer jet broken (3.5 (a))**Advice** Outer sill covers fitted**Advice** Under trays fitted

**MOT #5** 2017-11-09 11:02**MOT test number** 660070375206**Result** ✓ Passed**Advice** Both front tyres worn on inner edges**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** O/s/r tyre unevenly worn on inner edge**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #4** 2016-11-19 11:57**MOT test number** 237226008888**Result** ✓ Passed**MOT #3** 2016-11-18 14:41**MOT test number** 976435436724**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm offside front (4.1.E.1)**Advice** Remove items from drivers view**Fail** Tyre tread depth below requirements of 1.6mm nearside front (4.1.E.1)**Fail** Tyre tread depth below requirements of 1.6mm nearside rear (4.1.E.1)**Advice** Adjust internal headlight switch**MOT #2** 2015-10-19 09:50**MOT test number** 742332263033**Result** ✓ Passed**Advice** Advise both front tyres worn on edges



MOT #1	2014-10-24 09:39
MOT test number	516767594208
Result	✓ Passed
Advice	Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RO61HKK
Plate since	2019-09-28
Current registration	RO61HKK
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-25
Last registration	2023-07-18
Complete history	See info



Registration #1	2011-10-25	26 mi
Registration #2	2014-10-24	27.471 mi
Registration #3	2015-10-19	39.427 mi
Registration #4	2016-11-18	52.694 mi
Registration #5	2016-11-19	52.722 mi
Registration #6	2017-11-09	68.098 mi
Registration #7	2018-11-16	76.069 mi
Registration #8	2018-11-19	76.134 mi
Registration #9	2019-05-20	76.200 mi
Registration #10	2019-05-20	76.267 mi
Registration #11	2019-05-20	76.334 mi
Registration #12	2019-05-20	76.401 mi
Registration #13	2019-05-20	76.468 mi
Registration #14	2019-05-20	76.535 mi
Registration #15	2019-05-20	76.602 mi
Registration #16	2019-05-20	76.669 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1455 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	4530424
---------------	---------