



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Red
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 1

Date	2021-07-12
Pictures	4
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT #19	2021-02-25 14:42
MOT test number	924572540507
Result	✓ Passed
Next expiry date	2022-02-25

MOT #18	2021-02-23 16:00
MOT test number	179792159848
Result	✗ Failed

**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Fail** Offside Front Lower Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting outer sill area (6.2.2 (d) (i))

**Fail** Nearside Front Lower Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting outer sill area (6.2.2 (d) (i))

MOT #17	2020-02-26 12:43
MOT test number	671517005134
Result	✓ Passed

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2020-02-26 12:43
MOT test number	278704496331
Result	✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2019-02-26 11:57
MOT test number	508248973189
Result	✓ Passed

**MOT #14** 2018-02-08 10:41**MOT test number** 248872005086**Result** ✓ Passed**MOT #13** 2017-02-09 13:38**MOT test number** 789621349942**Result** ✓ Passed**Advice** Offside Rear tyre splitting in tread**MOT #12** 2017-02-08 09:42**MOT test number** 201428265972**Result** ✗ Failed**Fail** Nearside Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)**Advice** Offside Rear tyre splitting in tread**Fail** Offside Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)**MOT #11** 2016-02-11 09:55**MOT test number** 843764874968**Result** ✓ Passed**Advice** Centre exhaust outer casing corroded and rear exhaust strap deteriorated**Advice** Nearside Front Vehicle structure has slight corrosion outer sill (6.1.A.1)**Advice** Both front tyres worn on edges**Advice** Nearside Front Front position lamp(s) has a product on the light source but not adversely affecting light output dim (1.1.A.3d)**Advice** Offside Front Vehicle structure has slight corrosion outer sill (6.1.A.1)

**MOT #10** 2015-02-11 09:48**MOT test number** 117892345440**Result** ✓ Passed**Notice** Centre exhaust outer casing slight corrosion and rear exhaust strap deteriorated**MOT #9** 2014-02-10 16:38**MOT test number** 505681344059**Result** ✓ Passed**MOT #8** 2014-02-10 16:38**MOT test number** 456741344024**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp not working on main beam (1.7.5a)**MOT #7** 2013-02-11 14:27**MOT test number** 487922543068**Result** ✓ Passed**Notice** Offside rear tyre splitting**Notice** Exhaust rear strap corroded**MOT #6** 2012-02-13 12:01**MOT test number** 939744142007**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Rear wiper blade spli**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2012-02-13 10:24**MOT test number** 759304442068**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Notice** Rear wiper blade spli**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2010-10-16 16:37**MOT test number** 904079180260**Result** ✓ Passed**MOT #3** 2010-10-16 09:36**MOT test number** 181839680280**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Nearside Front Headlamp aim too high (1.8)**MOT #2** 2009-10-03 10:01**MOT test number** 371046879492**Result** ✓ Passed



MOT #1	2009-10-03 10:01
MOT test number	300116779404
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-03-28
Current registration	 
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-13
Last registration	2021-02-25
Complete history	<a href="#">See info</a>



Registration #1	2006-10-13	11 mi
Registration #2	2009-10-03	23.086 mi
Registration #3	2010-10-16	38.014 mi
Registration #4	2010-10-16	38.014 mi
Registration #5	2012-02-13	44.716 mi
Registration #6	2012-02-13	44.716 mi
Registration #7	2013-02-11	48.643 mi
Registration #8	2014-02-10	52.591 mi
Registration #9	2015-02-11	56.969 mi
Registration #10	2016-02-11	60.998 mi
Registration #11	2016-02-25	60.998 mi
Registration #12	2016-02-25	60.998 mi
Registration #13	2016-02-25	60.998 mi
Registration #14	2016-02-25	60.998 mi
Registration #15	2016-02-25	60.998 mi
Registration #16	2016-02-25	60.998 mi
Registration #17	2016-02-25	60.998 mi
Registration #18	2016-02-25	60.998 mi
Registration #19	2016-02-25	60.998 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3097262