




report date: 2024-03-29

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Blue
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-01-21
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-06
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	22
Total items failed	11

MOT #17	2024-02-01 16:51
MOT test number	992551288223
Result	✓ Passed
Next expiry date	2025-02-06
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2024-02-01 09:58
MOT test number	594023724545
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Bonnet primary retaining device ineffective (3.1 (c))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #15	2023-02-03 14:53
MOT test number	886650810844
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2023-02-03 14:53**MOT test number** 530078159736**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Bonnet cannot be secured in the closed position (3.1 (b) (i))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #13** 2022-01-10 09:53**MOT test number** 450549619748**Result** ✓ Passed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2021-01-12 10:06**MOT test number** 545807838963**Result** ✓ Passed**MOT #11** 2021-01-12 10:06**MOT test number** 847917160573**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid reservoir was empty (3.5 (a))**MOT #10** 2020-01-31 11:24**MOT test number** 273659786793**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** All direction indicators slightly discoloured (4.4.3 (a))

**MOT #9** 2019-01-31 09:33**MOT test number** 530263614976**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Engine oil level slightly low**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-02-02 13:07**MOT test number** 275562461860**Result** ✓ Passed**MOT #7** 2017-02-07 11:36**MOT test number** 577043209335**Result** ✓ Passed**MOT #6** 2017-02-06 14:06**MOT test number** 787334685449**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Trailing arm rubber bush deteriorated resulting in excessive movement N/S & O/S (2.4.G.2)**MOT #5** 2016-06-28 15:00**MOT test number** 561823097900**Result** ✓ Passed**Advice** Under trays fitted obscuring some underside components

**MOT #4** 2016-06-28 13:28**MOT test number** 482650518470**Result** ✗ Failed**Advice** Under trays fitted obscuring some underside components**Fail** Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**MOT #3** 2015-06-22 17:02**MOT test number** 847253375156**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Notice** Under-trays fitted obscuring some underside components**Notice** Tow ball/hitch not fitted at time of test**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #2** 2014-06-19 13:45**MOT test number** 396760474169**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-07-10 13:56**MOT test number** 765751393150**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
6 February 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	6 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-01
Last registration	2024-02-01
Complete history	See info



Registration #1	2010-09-01	24 mi
Registration #2	2013-07-10	20.401 mi
Registration #3	2014-06-19	33.061 mi
Registration #4	2015-06-22	53.150 mi
Registration #5	2016-06-28	70.451 mi
Registration #6	2016-06-28	70.452 mi
Registration #7	2017-02-06	76.555 mi
Registration #8	2017-02-07	76.555 mi
Registration #9	2018-02-02	79.322 mi
Registration #10	2019-01-31	81.054 mi
Registration #11	2019-01-31	81.054 mi
Registration #12	2019-01-31	81.054 mi
Registration #13	2019-01-31	81.054 mi
Registration #14	2019-01-31	81.054 mi
Registration #15	2019-01-31	81.054 mi
Registration #16	2019-01-31	81.054 mi
Registration #17	2019-01-31	81.054 mi
Registration #18	2019-01-31	81.054 mi
Registration #19	2019-01-31	81.054 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080