



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	-
Top speed	102 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-09
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #17</b>	2022-09-22 12:20
<b>MOT test number</b>	181932580232
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-09-29
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
<b>Advice</b>	Exhaust flexi slightly deteriorated.
<b>Advice</b>	Subframe mounting prescribed area is corroded but not considered excessive Front and Rear. (5.3.6 (a) (i))
<b>Minor</b>	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Rear Brake hose has slight corrosion to ferrule Both. (1.1.12 (f) (i))

<b>MOT #16</b>	2021-09-14 12:15
<b>MOT test number</b>	963006624598
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2020-09-30 09:07
<b>MOT test number</b>	879224545323
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

<b>MOT #14</b>	2019-07-09 09:44
<b>MOT test number</b>	231111686784
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2018-07-04 08:54
<b>MOT test number</b>	631929773243
<b>Result</b>	✓ Passed

**MOT #12**

2017-07-14 09:33

**MOT test number**

526161473533

**Result**

✓ Passed

**Advice**

Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #11**

2016-07-29 09:41

**MOT test number**

654436088039

**Result**

✓ Passed

**Advice**

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #10**

2016-07-29 09:41

**MOT test number**

519324332473

**Result**

✗ Failed

**Pass with rectification**

Offside Registration plate lamp not working (1.1.C.1d)

**Advice**

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #9**

2015-08-03 09:48

**MOT test number**

478205615239

**Result**

✓ Passed

**Advice**

Centre Exhaust has a minor leak of exhaust gases (7.1.2)

**Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2014-08-12 12:00

**MOT test number**

815254724213

**Result**

✓ Passed

**Advice**

Front Exhaust has a minor leak of exhaust gases (7.1.2)

**Notice**

N/s rear tyre wearing on outer edge

**MOT #7** 2013-08-16 10:06**MOT test number** 398008923297**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Notice** Nearside Front Tyre Worn On Outer Edge**MOT #6** 2013-08-16 10:06**MOT test number** 137068823253**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Notice** Nearside Front Tyre Worn On Outer Edge**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2012-06-23 10:24**MOT test number** 199575272182**Result** ✓ Passed**MOT #4** 2011-06-20 09:44**MOT test number** 527681071162**Result** ✓ Passed**MOT #3** 2010-06-29 09:03**MOT test number** 414640180152**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2009-06-29 09:15
MOT test number	981690189191
Result	✓ Passed

MOT #1	2008-06-27 12:28
MOT test number	693269378184
Result	✓ Passed

**Advice**    Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>GV05ZPM</b>
Plate since	2024-03-29
Current registration	<b>GV05ZPM</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-06-30
Last registration	2022-09-22
Complete history	<a href="#">See info</a>



Registration #1	2005-06-30	22 mi
Registration #2	2008-06-27	12.242 mi
Registration #3	2009-06-29	22.959 mi
Registration #4	2010-06-29	30.732 mi
Registration #5	2011-06-20	39.543 mi
Registration #6	2012-06-23	50.859 mi
Registration #7	2013-08-16	56.489 mi
Registration #8	2014-08-12	60.338 mi
Registration #9	2015-08-03	64.675 mi
Registration #10	2016-08-03	68.338 mi
Registration #11	2017-08-03	72.001 mi
Registration #12	2018-08-03	75.664 mi
Registration #13	2019-08-03	79.327 mi
Registration #14	2020-08-03	82.990 mi
Registration #15	2021-08-03	86.653 mi
Registration #16	2022-08-03	90.316 mi
Registration #17	2023-08-03	93.979 mi
Registration #18	2024-08-03	97.642 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1095 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EA4688403