



P250KVM

report date: 2024-03-29

General information

Make	VOLVO
Model	900 Series 940SELPT96
Colour	White
Year of manufacture	1996
Top speed	112 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	230 Nm at 2.300 rpm
Engine capacity	2.316 cc
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-07
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-13
MOT pass rate	60 %
MOT passed	18
Failed MOT tests	12
Total advice items	59
Total items failed	19

MOT #30 2023-06-21 12:22

MOT test number 776104016644

Result ✓ Passed

Next expiry date 2024-07-13

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))

Minor Hazard warning switch faulty Damaged But Functional (4.4.2 (a) (i))

Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d))

Advice Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))

MOT #29 2022-07-14 13:10

MOT test number 771629913072

Result ✓ Passed

MOT #28 2022-07-13 16:04

MOT test number 298088981430

Result ✗ Failed

Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #27**

2021-05-28 08:21

MOT test number

795591002819

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Oil leak.**MOT #26**

2020-06-05 09:07

MOT test number

699241561508

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Trailing (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Corrosion to NSF inner wheel arch**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Trailing (5.3.4 (a) (i))**MOT #25**

2019-05-14 09:29

MOT test number

521395476402

Result

✓ Passed

**MOT #24**

2018-05-25 11:26

MOT test number

369008642530

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #23

2018-05-21 08:49

MOT test number

770538067894

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Power steering component leaking rack (2.1.5 (a))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #22

2017-05-19 15:16

MOT test number

719140051068

Result

✓ Passed

MOT #21

2017-05-17 11:05

MOT test number

987528325575

Result

✗ Failed

- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #20** 2016-05-12 07:30**MOT test number** 768409613680**Result** Passed**MOT #19** 2016-05-11 14:14**MOT test number** 177311165910**Result** Failed**Fail** Nearside Front Steering system has a road wheel fouling a part of the vehicle (2.2.D.2a)**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #18** 2015-05-21 11:29**MOT test number** 875711845189**Result** Passed**MOT #17** 2015-05-20 09:36**MOT test number** 477380145199**Result** Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #16** 2014-05-14 16:49**MOT test number** 217404034122**Result** Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #15** 2014-05-14 08:58**MOT test number** 766044534104**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2013-05-16 14:51**MOT test number** 129936833189**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** 'oil leak**MOT #13** 2013-05-16 09:43**MOT test number** 509956233185**Result** ✗ Failed**Notice** Hand brake cable insecure**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** 'oil leak**Fail** Electrical wiring insecure (1.9.2a)**MOT #12** 2012-05-09 16:57**MOT test number** 815480432186**Result** ✓ Passed**Advice** Steering system slightly rough (2.2.D.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #11	2012-05-09 12:16
MOT test number	709490332160
Result	✗ Failed
Fail	Rear Exhaust has a major leak of exhaust gases (7.1.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Steering system slightly rough (2.2.D.1)

MOT #10	2011-05-04 15:22
MOT test number	847234321136
Result	✓ Passed
Notice	Both front wiper blades split.
Advice	Offside Ball joint has slight play (2.2.B.1f)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Ball joint has slight play (2.2.B.1f)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #9** 2011-04-28 14:57**MOT test number** 555098911191**Result** ✗ Failed

- Advice** Nearside Ball joint has slight play (2.2.B.1f)
- Fail** Nearside Front position lamp(s) insecure (1.1.A.3a)
- Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Fail** Rear registration plate deteriorated (6.3.1d)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Fail** Offside Front Tie bar/rod rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Offside Ball joint has slight play (2.2.B.1f)
- Fail** Nearside Front Direction indicator insecure (1.4.A.2b)
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Notice** Both front wiper blades split.
- Fail** Nearside Front Tie bar/rod rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #8 2010-05-12 17:39**MOT test number** 374172630120**Result** ✓ Passed

**MOT #7** 2010-05-12 12:11**MOT test number** 894402630134**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2009-05-12 17:49**MOT test number** 891452839126**Result** ✓ Passed**Advice** Nearside Power steering component(s) has slight seepage from a seal (2.3.3b)**Notice** Rear number plate deteriorating.**MOT #5** 2009-05-12 09:00**MOT test number** 263052839475**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Notice** Rear number plate deteriorating.**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**Advice** Nearside Power steering component(s) has slight seepage from a seal (2.3.3b)**MOT #4** 2008-05-16 16:33**MOT test number** 670807538150**Result** ✓ Passed**MOT #3** 2008-05-16 12:50**MOT test number** 280107838490**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)



MOT #2	2007-05-02 09:20
MOT test number	430572327135
Result	✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (3.6.B.4d)
Advice	Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

MOT #1	2006-05-10 12:46
MOT test number	713410336167
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 March
------------	---------------------

Days left	307
-----------	-----

MOT expiry date	13 July 2024
-----------------	--------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	1996-11-04
Last registration	2023-06-21
Complete history	See info



Registration #1	1996-11-04	29 mi
Registration #2	2006-05-10	97.756 mi
Registration #3	2007-05-02	103.470 mi
Registration #4	2008-05-16	113.244 mi
Registration #5	2008-05-16	113.244 mi
Registration #6	2009-05-12	120.914 mi
Registration #7	2009-05-12	120.914 mi
Registration #8	2010-05-12	128.364 mi
Registration #9	2010-05-12	128.364 mi
Registration #10	2011-04-28	136.222 mi
Registration #11	2011-05-04	136.222 mi
Registration #12	2012-05-09	144.530 mi
Registration #13	2012-05-09	144.530 mi
Registration #14	2013-05-16	148.124 mi
Registration #15	2013-05-16	148.124 mi
Registration #16	2014-05-14	149.718 mi
Registration #17	2015-05-20	151.312 mi
Registration #18	2015-05-20	151.312 mi
Registration #19	2015-05-20	151.312 mi
Registration #20	2015-05-20	151.312 mi
Registration #21	2015-05-20	151.312 mi
Registration #22	2015-05-20	151.312 mi
Registration #23	2015-05-20	151.312 mi
Registration #24	2015-05-20	151.312 mi
Registration #25	2015-05-20	151.312 mi
Registration #26	2015-05-20	151.312 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442
Registration #31	2025-25-25	25,252 442
Registration #32	2025-25-25	25,252 442

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Additional information

Number of axles	2
Engine number	6762