



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | PEUGEOT |
| Model | 308 BLUE HDI S/S GT LINE |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 132 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 150 BHP |
| Max. torque | 370 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 65.7 mpg |
| Consumption extra urban | 83.1 mpg |
| Consumption combined | 76.4 mpg |
| CO2 emission | 97 g/km |
| CO2 label | A |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-03-05 |
| Pictures | 19 |
| Listing price | View report |



source: yesauto.com

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-01-30 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 20 |
| Total items failed | 3 |

| | |
|-------------------------|---|
| MOT #8 | 2024-01-31 16:41 |
| MOT test number | 185135477023 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-30 |
| Advice | Nearside Rear Tyre read low, cracked/perished, 2 x Nail in tyre & small bulge outer tyre wall |

| | |
|------------------------|------------------|
| MOT #7 | 2022-12-12 14:15 |
| MOT test number | 904704315977 |
| Result | ✓ Passed |

| | |
|------------------------|--|
| MOT #6 | 2021-12-01 16:41 |
| MOT test number | 328836230142 |
| Result | ✓ Passed |
| Advice | Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

**MOT #5**

2021-12-01 16:41

MOT test number

905971291245

Result**✗ Failed****Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #4**

2020-12-08 08:12

MOT test number

589887911051

Result**✓ Passed****Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #3**

2019-12-18 09:52

MOT test number

726574399277

Result**✓ Passed****Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



| | |
|-----------------|------------------|
| MOT #2 | 2018-12-28 12:16 |
| MOT test number | 629758114463 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2018-12-28 10:10 |
| MOT test number | 758175327582 |
| Result | ✗ Failed |

- Fail

Nearside Front Direction indicator likely to become detached (4.4.1 (c) (ii))
- Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Front Fog light loose damaged



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
30 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 307 |
| MOT expiry date | 30 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  LB65AZD |
| Plate since | 2019-09-28 |
| Current registration |  LB65AZD |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2016-01-14 |
| Last registration | 2024-01-31 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2016-01-14 | 28 mi |
| Registration #2 | 2018-12-28 | 55.748 mi |
| Registration #3 | 2018-12-28 | 55.748 mi |
| Registration #4 | 2019-12-18 | 67.827 mi |
| Registration #5 | 2020-12-08 | 83.901 mi |
| Registration #6 | 2021-12-08 | 95.977 mi |
| Registration #7 | 2022-12-08 | 108.053 mi |
| Registration #8 | 2023-12-08 | 120.129 mi |
| Registration #9 | 2024-01-31 | 132.205 mi |
| Registration #10 | 2024-01-31 | 144.281 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 92% |
| Children | 79% |
| Pedestrian | 64% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1804 mm |
| Height | 1457 mm |
| Length | 4253 mm |
| Wheel base | 2620 mm |
| Kerb weight | 1290 kg |
| Max. allowed weight | 1870 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|-------------|
| Number of axles | 2 |
| Engine number | DYZJ4034304 |