





report date: 2024-03-29

### General information

Make	MINI
Model	COOPER D AUTO COOPER D
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

### Entry 2

Date 2021-09-16

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-15

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT expiry date	2023-10-05
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	7
Total items failed	9

MOT #12	2022-10-06 15:08
MOT test number	547914186733
Result	✓ Passed
Next expiry date	2023-10-05

MOT #11	2022-10-06 08:04
MOT test number	274978809301
Result	<b>X</b> Failed
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #10	2021-10-06 15:19
MOT test number	185140833528
Result	✓ Passed
Advice Nearside Rear Inner Nail in tyre edge not repairable	

MOT #9	2021-04-07 16:10
MOT test number	356695144689
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #8

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number

Result

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6

MOT test number

Result

Advice Nearside Rear Road wheel slightly distorted inner bead (5.2.2 (c) (i))

MOT test number

Result

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Road wheel slightly distorted inner bead (5.2.2 (c) (i))

 MOT #4
 2017-03-23 14:57

 MOT test number
 591232587817

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #32016-10-20 11:53MOT test number164950852237Result✓ PassedMOT #22016-10-20 11:53MOT test number912279203139ResultX FailedPass with rectificationOffside Registration plate lamp not working (1.1.C.1d)

**MOT #1** 2016-09-23 10:05 **MOT** test number 657663446829 Result × Failed Fail Nearside Front Inner Road wheel bead rim badly distorted (4.2.A.1a) **Advice** Nearside Rear nail in tyre. Fail Nearside Front Front position lamp(s) not working (1.1.A.3b) Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3) Fail Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b) Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

$\alpha$	vner	hi	ctc	1
$\cup$	viiei	ш	SIL	ע ונ

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		e?
THE STATE OF THE S		
***************************************		
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-18
Last registration	2022-10-06
Complete history	See info



Registration #1	2013-10-18	6 mi
Registration #2	2016-09-23	32.144 mi
Registration #3	2016-10-20	33.151 mi
Registration #4	2016-10-20	33.151 mi
Registration #5	2017-03-23	36.068 mi
Registration #6	2018-06-09	43.355 mi
Registration #7	2018-06-12	43.392 mi
Registration #8	2020-06-04	56.613 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

### Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1225 kg
Max. allowed weight	1655 kg

## Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 11/:

Number of axles 2

Engine number 71578581