





report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER HDI S L2 750
Colour	Blue
Year of manufacture	2016
Top speed	99 mph
0 - 60 mph	15.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-17

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	22
Total items failed	9

MOT #9		2023-09-29 16:01
MOT test	number	716763551184
Result		✓ Passed
Next expi	ry date	2024-09-28
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 1.8mm (5.2.	3 (e))
Advice bush deter	Nearside Front Suspension arm pin or bush worn but not resulting in exciorated (5.3.4 (a) (i))	xcessive movement rear
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.3	1.14 (a) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorated (5.3.4 (a) (i))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #8 2023-09-29 10:05

MOT test number 962609081676

Result X Failed

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorated (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail Offside Rear Valve stem seriously damaged (5.2.3 (j))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorated (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #7 2022-09-07 09:44

MOT test number 229131083489

Advice Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2021-09-13 10:28

MOT test number 683609366973

CarCheck.co.uk page 4/11



Result

Result

HK65VDC

report date: 2024-03-29

× Failed

× Failed

 MOT #5
 2021-02-12 10:09

 MOT test number
 586141369324

Result Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-02-12 10:09

MOT test number 909853235642

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #3 2020-02-10 17:13

MOT test number 488819216827

Result \(\sqrt{Passed} \)

Advice Rear Axle bushes slightly deteriorated but not resulting in excessive movement

MOT #2 2019-02-08 08:46

MOT test number 918420723518

Result

✓ Passed

MOT #1 2019-02-07 15:38

MOT test number 970847068258

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

e mier meerty	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-02-29
Last registration	2023-09-29
Complete history	See info



Registration #1	2016-02-29	23 mi
Registration #2	2019-02-07	30.730 mi
Registration #3	2019-02-08	30.730 mi
Registration #4	2020-02-10	39.281 mi
Registration #5	2021-02-12	48.963 mi
Registration #6	2021-02-12	48.963 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 au

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	2112 mm
Height	1832 mm
Length	4628 mm
Kerb weight	1289 kg
Max. allowed weight	2130 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	JBEM0461564

CarCheck.co.uk page 11/11