



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Grey
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	392 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #13	2024-04-09 11:11
MOT test number	214023819594
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Nearside Front Tyre worn close to legal limit/worn on edge heavily worn on edge 225/55R18 also on 2.1mm (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge heavily worn on edge 225/55R18 (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt

MOT #12	2023-04-12 15:21
MOT test number	763860847621
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 225/55R18 (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2023-04-05 13:07**MOT test number** 226020803995**Result** ✗ Failed**Fail** Offside Side repeater light intensity significantly reduced Led (4.4.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 225/55R18 (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2022-03-14 17:05**MOT test number** 480712259888**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing Both rear tyres perished (5.2.3 (d) (ii))**MOT #9** 2022-03-10 10:38**MOT test number** 791766870043**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Tyre slightly damaged/cracking or perishing Both rear tyres perished (5.2.3 (d) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Tyre worn close to legal limit/worn on edge Both fronts worn on inner and outer edges (5.2.3 (e))**MOT #8** 2021-02-15 11:28**MOT test number** 118673318440**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #7** 2020-02-13 11:52**MOT test number** 917926653251**Result** ✓ Passed**MOT #6** 2019-02-27 12:07**MOT test number** 251489800302**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view ZONE B (3.2 (a) (i))**MOT #5** 2018-02-16 16:20**MOT test number** 740471538418**Result** ✓ Passed**Advice** Offside Front wiper smearing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2017-02-17 15:11**MOT test number** 424981782241**Result** ✓ Passed**MOT #3** 2016-03-02 09:58**MOT test number** 667306461377**Result** ✓ Passed**Advice** Nearside front tyre starting to wear low 3mm 225/55/18**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2015-03-13 12:48**MOT test number** 889132975051**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2015-03-11 10:11**MOT test number** 565880375076**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
11 April 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EK12KHD
Plate since	2019-03-28
Current registration	EK12KHD
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-12
Last registration	2024-04-09
Complete history	See info



Registration #1	2012-03-12	6 mi
Registration #2	2015-03-11	34.850 mi
Registration #3	2015-03-13	34.883 mi
Registration #4	2016-03-02	44.342 mi
Registration #5	2017-02-17	54.963 mi
Registration #6	2018-02-16	62.529 mi
Registration #7	2019-02-27	69.613 mi
Registration #8	2020-02-13	76.110 mi
Registration #9	2021-02-27	82.617 mi
Registration #10	2022-02-27	89.124 mi
Registration #11	2023-02-27	95.631 mi
Registration #12	2024-02-27	102.138 mi
Registration #13	2025-02-27	108.645 mi
Registration #14	2026-02-27	115.152 mi
Registration #15	2027-02-27	121.659 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4HACU571054