





General information

Make	PEUGEOT
Model	HORIZON BLUE HDI S/S TEPEE ALLURE
Colour	Blue
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В







Internet history

Entry 1

Date

2021-11-16

8

Pictures

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	7
Total items failed	5

MOT #9	2023-08-03 09:29
MOT test number	528529998726
Result	✓ Passed
Next expiry date	2024-08-09
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #8	2022-08-10 12:21
MOT test number	317698486181
Result	✓ Passed
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	





MOT #7	2022-08-10 10:34
MOT test number	703511393255
Result	🗙 Failed
Fail Offside Registration plate lamp inoperative in the case of a single lamp or all	lamps (4.7.1 (b) (ii))
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Nearside Registration plate lamp inoperative in the case of a single lamp or a	all lamps (4.7.1 (b) (ii))
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

МОТ #6	2021-12-06 11:52
MOT test number	483382559212
Result	✓ Passed
MOT #5	2021-09-07 12:52
MOT test number	880010915260

Result

МОТ #4	2021-09-07 10:21
MOT test number	265605471833
Result	🗙 Failed
AdviceTpms light shows low tyre pressureFailNearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #3	2020-08-27 09:15
MOT test number	353113632960
Result	✓ Passed

🗸 Passed





🗸 Passed

MOT #2	2020-08-27 08:47
MOT test number	968736706633
Result	🗙 Failed
Fail Offside Rear Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i))	
MOT #1	2019-08-27 13:26
MOT test number	316114093956

Result



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 9 August 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	9 August 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-15
Last registration	2023-08-03
Complete history	See info



Registration #1	2016-09-15	19 mi
Registration #2	2019-08-27	3.890 mi
Registration #3	2020-08-27	7.538 mi
Registration #4	2020-08-27	7.539 mi
Registration #5	2021-09-07	15.497 mi
Registration #6	2021-09-07	15.498 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 est





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

Number of doors

Number of seats

Number of axles CarCheck.co.uk

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection

5

5

2

Engine number

JBHB3076096