



report date: 2024-03-28

General information

Make	BMW
Model	114 114D SE
Colour	White
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	235 Nm at 2.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-28
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	9
Total items failed	9

MOT #12	2023-07-27 18:02
MOT test number	689447416508
Result	✓ Passed
Next expiry date	2024-07-26

MOT #11	2022-07-18 09:27
MOT test number	377520144395
Result	✓ Passed
Advice	Undertrays and covers fitted obscuring some underside components
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

MOT #10	2021-07-19 13:11
MOT test number	714486580256
Result	✓ Passed

MOT #9	2020-12-14 16:32
MOT test number	586589010220
Result	✓ Passed

**MOT #8** 2020-12-14 14:26**MOT test number** 797948430638**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #7** 2019-12-16 16:21**MOT test number** 455056619557**Result** ✓ Passed**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2019-12-16 12:46**MOT test number** 683538098699**Result** ✗ Failed**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Front All position lamps have a product on the lenses or light sources which significantly reduces light intensity (4.2.3 (b) (ii))**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-12-18 16:27**MOT test number** 992571201286**Result** ✓ Passed

**MOT #4** 2018-12-18 12:26**MOT test number** 951727651841**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-12-11 13:21**MOT test number** 944814582133**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2016-12-09 16:22**MOT test number** 915967796571**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2016-12-09 11:38**MOT test number** 700178694390**Result** ✗ Failed**Fail** Offside Side repeater has less than 50% of the light sources illuminating (1.4.A.2c)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	LL63RXD
Plate since	2019-09-28
Current registration	LL63RXD
Plate since	2019-09-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-12-20
Last registration	2023-07-27
Complete history	See info



Registration #1	2013-12-20	28 mi
Registration #2	2016-12-09	35.738 mi
Registration #3	2016-12-09	35.738 mi
Registration #4	2017-12-11	47.626 mi
Registration #5	2018-12-18	60.259 mi
Registration #6	2018-12-18	60.259 mi
Registration #7	2019-12-16	75.741 mi
Registration #8	2019-12-16	75.741 mi
Registration #9	2019-12-16	75.741 mi
Registration #10	2019-12-16	75.741 mi
Registration #11	2019-12-16	75.741 mi
Registration #12	2019-12-16	75.741 mi
Registration #13	2019-12-16	75.741 mi
Registration #14	2019-12-16	75.741 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1984 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1310 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

72168416