



TOYOTA



report date: 2024-03-29

General information

|                     |                 |
|---------------------|-----------------|
| Make                | TOYOTA          |
| Model               | AVENSIS D-4D T4 |
| Colour              | Blue            |
| Year of manufacture | 2009            |
| Top speed           | 124 mph         |
| 0 - 60 mph          | 10.0 seconds    |
| Gearbox             | 6 speed Manual  |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 125 BHP             |
| Max. torque             | 310 Nm at 1.800 rpm |
| Engine capacity         | 1.998 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 42.8 mpg            |
| Consumption extra urban | 65.7 mpg            |
| Consumption combined    | 54.3 mpg            |
| CO2 emission            | 136 g/km            |
| CO2 label               | E                   |





MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-10-02 |
| MOT pass rate      | 67 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 5          |
| Total advice items | 42         |
| Total items failed | 6          |

MOT #152020-09-26 09:14

MOT test number796564326310

Result✓ Passed

Next expiry date2021-10-02

|        |   |
|--------|---|
| Advice | Dent in bonnet  |
| Advice | Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))                          |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i))  |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing Slight perishing (5.2.3 (d) (ii))  |
| Advice | Very slight corrosion on underside  |
| Advice | Offside Rear Direction indicator slightly discoloured (4.4.3 (a))                           |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing Slight perishing (5.2.3 (d) (ii)) |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i))   |
| Advice | Headlights discoloured  |

**MOT #14**

2020-09-23 09:20

**MOT test number**

252073484377

**Result****✗ Failed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Headlights discoloured
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slight perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Dent in bonnet
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Slight perishing (5.2.3 (d) (ii))
- Advice** Very slight corrosion on underside
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13**

2019-09-09 11:34

**MOT test number**

600691939418

**Result****✓ Passed**

- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))

**MOT #12**

2019-09-03 09:15

**MOT test number**

103339201202

**Result****✗ Failed****DANGEROUS** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**MOT #11**

2018-09-27 14:44

**MOT test number**

686866974253

**Result****✓ Passed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2017-10-03 13:48

**MOT test number**

963467628094

**Result****✓ Passed**

**MOT #9** 2017-10-03 11:40**MOT test number** 187274493740**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2017-01-28 10:25**MOT test number** 914583859996**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-01-27 11:42**MOT test number** 553282397808**Result** ✓ Passed**MOT #6** 2016-01-26 17:01**MOT test number** 147176887302**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2015-02-19 13:03**MOT test number** 739210755029**Result** ✓ Passed

**MOT #4** 2014-02-26 14:50**MOT test number** 836537054072**Result** ✓ Passed

**Advice** Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #3** 2014-02-26 14:50**MOT test number** 527977454035**Result** ✗ Failed

**Advice** Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)

**Advice** Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #2** 2013-02-20 12:23**MOT test number** 706731253080**Result** ✓ Passed**MOT #1** 2011-12-30 14:05**MOT test number** 448284461418**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-06-29 |
| Current registration | *****      |
| Plate since          | 2019-06-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2009-01-06               |
| Last registration          | 2020-09-26               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-01-06 | 9 mi      |
| Registration #2  | 2011-12-30 | 15.252 mi |
| Registration #3  | 2013-02-20 | 19.593 mi |
| Registration #4  | 2014-02-26 | 31.647 mi |
| Registration #5  | 2015-02-19 | 40.106 mi |
| Registration #6  | 2016-01-26 | 45.699 mi |
| Registration #7  | 2016-01-27 | 45.699 mi |
| Registration #8  | 2017-01-28 | 53.547 mi |
| Registration #9  | 2018-01-29 | 55.557 mi |
| Registration #10 | 2018-01-29 | 55.557 mi |
| Registration #11 | 2018-01-29 | 55.557 mi |
| Registration #12 | 2018-01-29 | 55.557 mi |
| Registration #13 | 2018-01-29 | 55.557 mi |
| Registration #14 | 2018-01-29 | 55.557 mi |
| Registration #15 | 2020-09-26 | 55.557 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 90%                             |
| Children       | 86%                             |
| Pedestrian     | 53%                             |
| Safety systems | 86%                             |
| Overall rating | 81%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1810 mm |
| Height              | 1480 mm |
| Length              | 4765 mm |
| Wheel base          | 2700 mm |
| Kerb weight         | 1635 kg |
| Max. allowed weight | 2130 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |            |
|------------------------|------------|
| <b>Number of axles</b> | 2          |
| <b>Engine number</b>   | 1AF5485102 |