




report date: 2024-03-29

General information

Make	VOLVO
Model	C70 T5 COLLECTION
Colour	Silver
Year of manufacture	2005
Top speed	143 mph
0 - 60 mph	8.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	330 Nm at 5.100 rpm
Engine capacity	2.319 cc
Cylinders	5
Fuel type	Petrol
Consumption city	17.7 mpg
Consumption extra urban	35.3 mpg
Consumption combined	25.9 mpg
CO2 emission	261 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-09-03
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-02
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-04-25
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #17	2021-04-26 12:20
MOT test number	404999798805
Result	✓ Passed
Next expiry date	2022-04-25
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2020-03-16 11:45
MOT test number	179538820940
Result	✓ Passed

MOT #15	2019-03-20 13:57
MOT test number	692639449499
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2019-03-18 11:38**MOT test number** 987291991373**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2018-03-13 15:05**MOT test number** 898568644910**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2018-03-08 13:04**MOT test number** 816884244663**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Brake pedal has insufficient reserve movement (3.3.A.5)**MOT #11** 2017-03-23 14:41**MOT test number** 862225598665**Result** ✓ Passed**Advice** Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #10**

2017-03-17 10:24

MOT test number

107986807402

Result**✗ Failed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both front (3.5.1i)**Advice** Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Brake pedal spongy (3.3.B.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened Both rear (3.5.1i)**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Fail** Battery insecure (1.9.1)**MOT #9**

2016-03-30 09:02

MOT test number

539704168621

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8**

2015-02-05 08:39

MOT test number

227936435065

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2014-01-29 12:55**MOT test number** 677619324034**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-01-30 10:30**MOT test number** 786970233009**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2012-01-17 10:56**MOT test number** 797207912073**Result** ✓ Passed**MOT #4** 2011-01-12 11:02**MOT test number** 127942611401**Result** ✓ Passed**MOT #3** 2010-01-22 14:15**MOT test number** 604672620096**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc slightly scored (3.5.1h)



MOT #2	2009-01-30 12:53
MOT test number	353910639050
Result	✓ Passed

MOT #1	2008-02-18 12:45
MOT test number	110249248083
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-01
Last registration	2021-04-26
Complete history	See info



Registration #1	2005-03-01	21 mi
Registration #2	2008-02-18	9.534 mi
Registration #3	2009-01-30	10.381 mi
Registration #4	2010-01-22	11.552 mi
Registration #5	2011-01-12	13.930 mi
Registration #6	2012-01-17	14.610 mi
Registration #7	2013-01-30	15.372 mi
Registration #8	2014-01-29	15.678 mi
Registration #9	2015-02-05	15.803 mi
Registration #10	2016-03-30	15.991 mi
Registration #11	2016-03-30	15.991 mi
Registration #12	2016-03-30	15.991 mi
Registration #13	2016-03-30	15.991 mi
Registration #14	2016-03-30	15.991 mi
Registration #15	2016-03-30	15.991 mi
Registration #16	2016-03-30	15.991 mi
Registration #17	2016-03-30	15.991 mi
Registration #18	2016-03-30	15.991 mi
Registration #19	2016-03-30	15.991 mi
Registration #20	2016-03-30	15.991 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	2660 mm
Length	4720 mm
Wheel base	1420 mm
Kerb weight	1565 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	3650478