




report date: 2025-01-18

General information

Make	CITROEN
Model	BX GT
Colour	White
Year of manufacture	1989
Top speed	107 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol





Internet history

Entry 1

Date	2023-07-27
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-08-07
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	37
Total items failed	11

MOT #19	2024-08-07 10:58
MOT test number	617858468601
Result	✓ Passed
Next expiry date	2025-08-07

MOT #18	2023-08-08 14:09
MOT test number	832680834530
Result	✓ Passed

MOT #17	2022-07-06 11:42
MOT test number	243733701101
Result	✓ Passed

Advice Oil leak engine and gear box

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated boot split or cracking leaking (6.1.7 (g) (i))



MOT #16 2022-07-06 09:34

MOT test number 678488584846

Result ✗ Failed

- MAJOR** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated boot split or cracking leaking (6.1.7 (g) (i))
- MAJOR** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- MAJOR** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Advice** Oil leak engine and gear box

MOT #15 2021-07-26 14:46

MOT test number 600815064345

Result ✓ Passed

- Advice** Nearside Front Brake hose slightly deteriorated cracking (1.1.12 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated cracking (1.1.12 (b) (ii))

MOT #14 2021-07-26 13:41

MOT test number 492196195479

Result ✗ Failed

- Advice** Nearside Front Brake hose slightly deteriorated cracking (1.1.12 (b) (ii))
- MAJOR** Horn not working (7.7 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated cracking (1.1.12 (b) (ii))



MOT #13 2020-07-31 08:41

MOT test number 564908302283

Result ✔ Passed

Advice Offside Front Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Unable to check brake pads

Advice Nearside Front Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Items removed from driver's view prior to test

MOT #12 2020-07-31 08:41

MOT test number 946360698360

Result ✘ Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Advice Items removed from driver's view prior to test

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Unable to check brake pads

Advice Nearside Front Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #11 2012-03-16 11:48

MOT test number 717136772058

Result ✔ Passed



MOT #10 2012-03-09 14:46

MOT test number 266679662086

Result ✗ Failed

- Fail** Fluid suspension leaking (2.4.D.2)
- Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)
- Fail** Offside Front Fluid suspension pipe leaking (2.4.D.2)
- Fail** Offside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #9 2011-03-18 10:25

MOT test number 708377871062

Result ✓ Passed

MOT #8 2010-03-22 10:52

MOT test number 233451180085

Result ✓ Passed

- Notice** Slight age cracks noted in offside rear tyre
- Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)
- Notice** Age cracks noted in spare tyre.
- Notice** Slight dampness noted in area of master cylinder
- Advice** Offside Steering rack gaiter deteriorated (2.2.D.2d)

MOT #7 2009-03-17 14:52

MOT test number 733796179071

Result ✓ Passed

- Notice** Slight fluid weep noted from front sphere area.
- Notice** Slight fluid weep noted from brake master cylinder area.



MOT #6 2009-03-16 10:32

MOT test number 854255779082

Result ✗ Failed

Fail Offside Front Fluid suspension pipe leaking (2.4.D.2)

Notice Slight fluid weep noted from front sphere area.

Fail Rear fog lamp switch faulty (1.3.1a)

Notice Slight fluid weep noted from brake master cylinder area.

MOT #5 2008-03-28 10:25

MOT test number 370128188057

Result ✓ Passed

MOT #4 2007-03-13 17:01

MOT test number 263882277038

Result ✓ Passed

MOT #3 2007-03-13 11:35

MOT test number 634962577014

Result ✗ Failed

Fail Nearside Outer Front constant velocity joint gaiter split (2.5.C.1a)

Fail Offside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #2 2006-03-15 09:45

MOT test number 634674776079

Result ✓ Passed



MOT #1 2006-03-14 15:20

MOT test number 104973476456

Result ✗ Failed

Notice Suspension starting to bounce

Fail Centre Rear Exhaust has a major leak of exhaust gases (7.1.2)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	F709LOD
Plate since	2019-09-29
Current registration	F709LOD
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1989-04-20
Last registration	2024-08-07
Complete history	See info



Registration #1	1989-04-20	29 mi
Registration #2	2006-03-14	20.138 mi
Registration #3	2006-03-15	20.138 mi
Registration #4	2007-03-13	20.950 mi
Registration #5	2007-03-13	20.950 mi
Registration #6	2008-03-28	21.503 mi
Registration #7	2009-03-16	22.020 mi
Registration #8	2009-03-17	22.020 mi
Registration #9	2010-03-22	22.291 mi
Registration #10	2011-03-18	22.745 mi
Registration #11	2012-03-09	22.799 mi
Registration #12	2013-03-09	22.853 mi
Registration #13	2013-03-09	22.853 mi
Registration #14	2013-03-09	22.853 mi
Registration #15	2013-03-09	22.853 mi
Registration #16	2013-03-09	22.853 mi
Registration #17	2013-03-09	22.853 mi
Registration #18	2013-03-09	22.853 mi
Registration #19	2013-03-09	22.853 mi
Registration #20	2013-03-09	22.853 mi
Registration #21	2024-08-07	29 mi

[More info >](#)



Dimensions & weight

Width	1560 mm
Height	1350 mm
Length	3500 mm

Additional information

Fuel tank capacity	43 l
Fuel delivery	Carburettor
Number of doors	3
Engine number	542006