



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER S
Colour	Black
Year of manufacture	2010
Top speed	142 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-04
Pictures	24
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-05-19
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #15	2023-05-09 15:24
MOT test number	139492709677
Result	✓ Passed
Next expiry date	2024-05-19
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2023-05-09 09:06
MOT test number	499763579126
Result	✗ Failed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #13**

2022-05-17 08:35

**MOT test number**

478936848034

**Result**

✓ Passed

**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2021-05-20 11:17

**MOT test number**

372311570407

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #11**

2021-05-20 08:30

**MOT test number**

192464366005

**Result**

✗ Failed

**Fail** Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))**Fail** Offside Rear Tyre has ply or cords exposed bald inner edge (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #10**

2020-07-13 08:26

**MOT test number**

917776425251

**Result**

✓ Passed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2019-07-11 10:44**MOT test number** 816751841265**Result** ✓ Passed**MOT #8** 2018-07-23 14:37**MOT test number** 543503888505**Result** ✓ Passed**MOT #7** 2018-07-18 12:31**MOT test number** 545399647884**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (i))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #6** 2017-07-06 13:45**MOT test number** 911432607669**Result** ✓ Passed**MOT #5** 2017-07-05 09:10**MOT test number** 635237006310**Result** ✗ Failed**Fail** Offside Front Inner Road wheel bead rim badly distorted (4.2.A.1a)**Advice** Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2016-10-03 14:49**MOT test number** 785726372667**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



<b>MOT #3</b>	2015-10-10 10:47
---------------	------------------

<b>MOT test number</b>	565423257979
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-10-03 14:47
---------------	------------------

<b>MOT test number</b>	879896774274
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
---------------	--

<b>Notice</b>	Under-trays fitted obscuring some underside components
---------------	--

<b>MOT #1</b>	2013-09-27 09:44
---------------	------------------

<b>MOT test number</b>	137800973242
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
---------------	--



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
19 May 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	19 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-25
Last registration	2023-05-09
Complete history	<a href="#">See info</a>



Registration #1	2010-10-25	25 mi
Registration #2	2013-09-27	28.470 mi
Registration #3	2014-10-03	35.431 mi
Registration #4	2015-10-10	42.531 mi
Registration #5	2016-10-03	48.497 mi
Registration #6	2017-07-05	51.291 mi
Registration #7	2017-07-06	51.291 mi
Registration #8	2018-07-18	58.119 mi
Registration #9	2018-07-23	58.175 mi
Registration #10	2019-05-20	59.377 mi
Registration #11	2019-05-20	59.377 mi
Registration #12	2019-05-20	59.377 mi
Registration #13	2019-05-20	59.377 mi
Registration #14	2019-05-20	59.377 mi
Registration #15	2019-05-20	59.377 mi
Registration #16	2019-05-20	59.377 mi
Registration #17	2019-05-20	59.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats 4

<b>Number of axles</b>	2
<b>Engine number</b>	A7111774