



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-09-24
Pictures	29
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-22
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	27
Total items failed	13

MOT #18	2023-09-23 14:59
MOT test number	278247179120
Result	✓ Passed
Next expiry date	2024-09-22
Advice	Under body component corroded,

MOT #17	2022-09-16 11:24
MOT test number	653757340286
Result	✓ Passed

MOT #16	2022-09-15 10:55
MOT test number	336406269306
Result	✗ Failed
Advice	Offside Brake cable damaged but not to excess outer casing cracked (1.1.15 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Service brake excessively fluctuating (1.2.1 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2021-09-23 09:16**MOT test number** 162673910391**Result** ✓ Passed**MOT #14** 2021-09-21 16:01**MOT test number** 338087940930**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #13** 2020-12-18 16:59**MOT test number** 540981131268**Result** ✓ Passed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front number plate cracked**Advice** Rear exhaust silencer badly corroded**Advice** Exhaust has a minor leak of exhaust gases front flexible joint (6.1.2 (a))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #12** 2020-12-18 12:05**MOT test number** 539699272390**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front brake discs worn**Advice** Exhaust has a minor leak of exhaust gases front flexible joint (6.1.2 (a))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front number plate cracked**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear exhaust silencer badly corroded**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #11** 2019-12-17 10:12**MOT test number** 547897677888**Result** ✓ Passed**Advice** Exhaust rear silencer outer skin badly corroded**MOT #10** 2018-12-18 09:38**MOT test number** 895462262127**Result** ✓ Passed**Advice** Child seat fitted in n/s rear , seat belt not checked**Advice** Exhaust rear silencer corroded

**MOT #9** 2018-01-05 11:33**MOT test number** 934486282516**Result** ✓ Passed**Advice** Exhaust rear silencer badly corroded**Advice** Child seat fitted In n/s rear, seat belt not fully checked**MOT #8** 2017-01-05 11:24**MOT test number** 999195996008**Result** ✓ Passed**Advice** Slight blow on exhaust front gasket/ rear box outer skin holed and corroded**MOT #7** 2017-01-05 11:24**MOT test number** 819557448890**Result** ✗ Failed**Advice** Slight blow on exhaust front gasket/ rear box outer skin holed and corroded**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-01-07 16:07**MOT test number** 496192151020**Result** ✓ Passed**MOT #5** 2016-01-07 12:05**MOT test number** 416365428120**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #4** 2015-01-07 10:59**MOT test number** 996287405017**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-01-13 16:00**MOT test number** 716863414068**Result** ✓ Passed**MOT #2** 2013-01-09 12:39**MOT test number** 748569203040**Result** ✓ Passed**MOT #1** 2012-01-04 11:19**MOT test number** 509394002011**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
22 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	22 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-01-29
Last registration	2023-09-23
Complete history	See info



Registration #1	2009-01-29	16 mi
Registration #2	2012-01-04	28.759 mi
Registration #3	2013-01-09	34.861 mi
Registration #4	2014-01-13	41.583 mi
Registration #5	2015-01-07	51.500 mi
Registration #6	2016-01-07	62.222 mi
Registration #7	2016-01-07	62.222 mi
Registration #8	2017-01-05	71.551 mi
Registration #9	2017-01-05	71.551 mi
Registration #10	2018-01-05	83.388 mi
Registration #11	2019-01-05	95.222 mi
Registration #12	2020-01-05	107.056 mi
Registration #13	2021-01-05	118.889 mi
Registration #14	2022-01-05	130.722 mi
Registration #15	2023-01-05	142.556 mi
Registration #16	2024-01-05	154.389 mi
Registration #17	2025-01-05	166.222 mi
Registration #18	2026-01-05	178.056 mi
Registration #19	2027-01-05	189.889 mi
Registration #20	2028-01-05	201.722 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694