




report date: 2024-03-29

General information

Make	CITROEN
Model	C4 GRAND E-HDI AIRDREAM EXCLUSIVE PLUS ETG6
Colour	Silver
Year of manufacture	2014
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B







Internet history

Entry 1

Date	2021-01-22
Pictures	13
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-02-26
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	9

MOT #11	2024-02-27 15:21
MOT test number	323908214514
Result	✓ Passed
Next expiry date	2025-02-26
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2024-02-27 15:21

MOT test number

341003308877

Result**✗ Failed****Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9**

2023-02-27 12:20

MOT test number

540275544918

Result**✓ Passed****Minor** Lower Window damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #8**

2023-02-20 15:21

MOT test number

403713954921

Result**✗ Failed****Fail** Offside Front Sub-frame pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Sub-frame pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #7** 2022-02-19 10:53**MOT test number** 705605549959**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Tyre worn close to legal limit/worn on edge both, extremely , on inner edges. (5.2.3 (e))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #6** 2021-02-22 16:57**MOT test number** 315890630434**Result** ✓ Passed**MOT #5** 2020-08-07 09:54**MOT test number** 375647797827**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Damage to nearside stil at front**MOT #4** 2019-08-20 08:20**MOT test number** 222281316607**Result** ✓ Passed**Advice** Slight damage to near side front sill**MOT #3** 2018-08-06 11:49**MOT test number** 925063439814**Result** ✓ Passed**MOT #2** 2017-09-05 14:05**MOT test number** 676726583475**Result** ✓ Passed



MOT #1	2017-08-17 10:45
MOT test number	424536054713
Result	✗ Failed
<div><div>Advice</div>Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)</div>	
<div><div>Fail</div>Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner sidewall (4.1.D.1b)</div>	
<div><div>Fail</div>Nearside Rear Rear wheel bearing rough when rotated (2.6.1)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-01
Last registration	2024-02-27
Complete history	See info



Registration #1	2014-09-01	17 mi
Registration #2	2017-08-17	38.653 mi
Registration #3	2017-09-05	38.748 mi
Registration #4	2018-08-06	53.575 mi
Registration #5	2019-08-20	70.945 mi
Registration #6	2020-08-07	83.525 mi
Registration #7	2021-08-20	96.105 mi
Registration #8	2022-08-20	108.685 mi
Registration #9	2023-08-20	121.265 mi
Registration #10	2024-02-27	133.845 mi
Registration #11		
Registration #12		
Registration #13		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1320 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBEX3019183