



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Blue
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-08
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	22
Total items failed	8

MOT #22	2024-02-06 09:59
MOT test number	304660373363
Result	✓ Passed
Next expiry date	2025-02-08
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #21	2023-01-26 12:40
MOT test number	115294441209
Result	✓ Passed

MOT #20	2022-02-08 14:21
MOT test number	466500550852
Result	✓ Passed

MOT #19	2022-02-08 14:21
MOT test number	468417932259
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #18** 2021-02-09 15:34**MOT test number** 902326906030**Result** ✓ Passed**MOT #17** 2020-08-07 13:10**MOT test number** 835764865648**Result** ✓ Passed**MOT #16** 2019-08-06 11:56**MOT test number** 904143195387**Result** ✓ Passed**MOT #15** 2019-08-05 13:01**MOT test number** 941135373019**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #14** 2018-08-06 08:58**MOT test number** 366192609608**Result** ✓ Passed**MOT #13** 2017-09-06 13:58**MOT test number** 808376849906**Result** ✓ Passed

**MOT #12** 2017-09-04 11:47**MOT test number** 245096580227**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2017-05-11 15:16**MOT test number** 819091963910**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2017-05-11 15:16**MOT test number** 316774276795**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-04-27 14:11**MOT test number** 906121565762**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #8** 2015-05-06 14:44**MOT test number** 386716225101**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2015-05-06 14:44**MOT test number** 629416025115**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Under-trays fitted obscuring some underside components**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2014-05-09 12:55**MOT test number** 515519724122**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-05-08 14:21**MOT test number** 948388223180**Result** ✓ Passed**MOT #4** 2012-05-09 11:00**MOT test number** 948090232128**Result** ✓ Passed



MOT #3	2012-05-09 11:00
MOT test number	819510332118
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)
Pass with rectification	Nearside Headlamp aim too high (1.8)

MOT #2	2011-05-16 10:50
MOT test number	336896931163
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2010-07-26 16:43
MOT test number	141317300222
Result	✓ Passed
Advice	Centre Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
8 February 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-08-08
Last registration	2024-02-06
Complete history	See info



Registration #1	2007-08-08	26 mi
Registration #2	2010-07-26	17.719 mi
Registration #3	2011-05-16	20.583 mi
Registration #4	2012-05-09	22.901 mi
Registration #5	2013-05-08	25.519 mi
Registration #6	2014-05-09	28.665 mi
Registration #7	2015-05-06	30.878 mi
Registration #8	2016-04-27	33.510 mi
Registration #9	2017-05-11	36.614 mi
Registration #10	2017-05-11	36.614 mi
Registration #11	2017-09-04	37.794 mi
Registration #12	2018-05-20	39.000 mi
Registration #13	2019-05-20	40.200 mi
Registration #14	2020-05-20	41.400 mi
Registration #15	2021-05-20	42.600 mi
Registration #16	2022-05-20	43.800 mi
Registration #17	2023-05-20	45.000 mi
Registration #18	2024-02-06	46.200 mi
Registration #19	2024-02-06	46.200 mi
Registration #20	2024-02-06	46.200 mi
Registration #21	2024-02-06	46.200 mi
Registration #22	2024-02-06	46.200 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Engine number	BMM 122233