





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5 STR
Colour	Black
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-08

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT #17

MOT test number

120009066547

Result

Next expiry date

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

MOT test number

Result

MOT #15

2020-07-21 16:27

666092964127

✓ Passed

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14 2018-08-14 15:48
MOT test number 876304238058
Result ✓ Passed

Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

 MOT #13
 2017-07-03 15:07

 MOT test number
 595435002694

 Result
 ✓ Passed

CarCheck.co.uk page 3/12



YK04JRF

report date: 2024-03-28

MOT #12 2016-07-04 15:43

MOT test number 828292067921

MOT #11 2015-06-06 18:20

MOT test number 919057555183

Result Passed

Notice Items removed from driver's view prior to test

Advice Nearside Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

MOT #10 2015-06-04 16:31

MOT test number 417695955144

Result X Failed

Advice Nearside Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

Notice Under-trays fitted obscuring some underside components

Fail Electronic stability system warning lamp indicates a fault (3.4.1c)

Notice Items removed from driver's view prior to test

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Notice Engine covers fitted obscuring some components in the engine bay

Fail Offside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 4/12



MOT #9

(2.4.G.2)

YKO4JRF report date: 2024-03-28

2014-06-10 11:51

MOT test number 867221764184

Result
✓ Passed

MOT #8 2013-03-21 10:09

MOT test number 479500683015

Result
✓ Passed

MOT #7 2012-03-23 15:51

MOT test number 716073782094

Result

Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2012-03-23 15:51

MOT test number 686513882076

Result × Failed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-02-27 15:56

MOT test number 799268352074

Notice Child seat fitted not allowing full inspection of adult belt

Notice Nail in nearside rear tyre

CarCheck.co.uk page 5/12



MOT #4	2011-02-18 10:39
MOT test number	387339741016
Result	✓ Passed
MOT #3	2009-07-14 11:40
MOT test number	911095699175
Result	✓ Passed
MOT #2	2008-07-14 15:03
MOT test number	873780852983
Result	✓ Passed
MOT #1	2007-07-16 10:00
MOT test number	833757997132
Result	✓ Passed

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-07-23
Last registration	2021-08-19
Complete history	See info



Registration #1	2004-07-23	16 mi
Registration #2	2007-07-16	34.301 mi
Registration #3	2008-07-14	47.632 mi
Registration #4	2009-07-14	56.019 mi
Registration #5	2011-02-18	73.318 mi
Registration #6	2012-02-27	78.018 mi
Registration #7	2012-03-23	78.108 mi
Registration #8	2013-03-21	81.400 mi
Registration #9	2014-06-10	84.928 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
	70/70

CarCheck.co.uk page 12/12

Number of seats	5
Engine number	AVQ 050944