





General information

Make	BMW
Model	125 125I SE
Colour	Black
Year of manufacture	2008
Top speed	148 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	218 BHP
Max. torque	270 Nm at 4.250 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	24.1 mpg
Consumption extra urban	47.1 mpg
Consumption combined	34.9 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 1

Date

Pictures

2021-08-27

2

Listing price

View report





source: yesauto.com



MOT history

MOT expiry date	2024-01-30
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	25
Total items failed	9

MOT #17	2023-01-19 09:58
MOT test number	188907397105
Result	✓ Passed
Next expiry date	2024-01-30
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Front Brakes imbalanced requirements only just met. It would appear that requires adjustment or repair. (1.2.1 (b) (i))	at the braking system

MOT #16		2022-01-25 11:38
MOT test	number	435483584295
Result		✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	

MOT #15	2021-01-14 09:30
MOT test number	988826556553
Result	✓ Passed





MOT #14		2020-01-24 10:10
MOT test	number	728392395275
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2019-01-25 13:45
MOT test number	422410600553
Result	✓ Passed

MOT #12	2019-01-25 11:40
MOT test number	107735134768
Result	🗙 Failed
Fail Bonnet cannot be secured in the closed position (3.1 (b) (i))	

MOT #11		2018-01-26 14:22
MOT test	number	148894240512
Result		✓ Passed
Advice	Offside Rear Valve stem slightly damaged (4.1.D.1e)	
Advice	Nearside Rear Valve stem slightly damaged (4.1.D.1e)	

MOT #10	2018-01-26 10:04
MOT test number	411260728784
Result	🗙 Failed
Fail Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Offside Rear Valve stem slightly damaged (4.1.D.1e)	
Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Nearside Rear Valve stem slightly damaged (4.1.D.1e)	





MOT #9	2017-01-31 11:41
MOT test number	644984125797
Result	✓ Passed
MOT #8	2017-01-31 11:41
MOT test number	102747820663
Result	× Failed
Pass with rectification (3.5.1k)	Nearside Front Mechanical brake component has restricted free movement
Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification (3.5.1k)	Offside Front Mechanical brake component has restricted free movement

MOT #7	2016-06-29 15:28
MOT test number	298919356877
Result	✓ Passed
Advice Covers fitted to engine bay and under side	

MOT #6	2016-06-28 13:36
MOT test number	937081222628
Result	🗙 Failed
Advice Covers fitted to engine bay and under side	
Advice Parking brake lever has little reserve travel (3.1.6b)	
Fail Nearside Rear rear brake excessively fluctuating (3.7.B.3)	
Fail Nearside Rear rear brake binding (3.7.B.1)	
Fail Offside Front Shock absorber has a serious fluid leak (2.7.3)	



SC08PNL
report date: 2024-03-28

MOT #5		2015-06-08 13:24
MOT test	number	756699455158
Result		✓ Passed
Notice	N/s/f brake binding	
Advice	Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Notice	Damage to n/s/r wheel arch	
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	

MOT #4	2014-06-18 10:03
MOT test number	658919664143
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2013-06-29 14:12
MOT test number	785830083136
Result	✓ Passed
MOT #2	2012-06-09 16:09
MOT test number	606111762163

Result

🗸 Passed





MOT #1	2011-06-09 15:29
MOT test number	697780461158
Result	✓ Passed
 Advice Parking brake: parking brake efficiency only just met. It would appear requires adjustment or repair. (3.7.B.7) Notice Child seat fitted not allowing full inspection of adult belt 	r that the braking system





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

-
AMP
- A

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes See in this check if this BMW had different number plates	5.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SCO8PNL report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-26
Last registration	2023-01-19
Complete history	<u>See info</u>



Registration #1	2008-06-26	16 mi
Registration #2	2011-06-09	31.084 mi
Registration #3	2012-06-09	40.870 mi
Registration #4	2013-06-29	44.229 mi
Registration #5	2014-06-18	54.452 mi
Registration #6	2015-06-08	64.246 mi
Registration #7	2016-06-28	76.040 mi
Registration #8	2016-06-29	76.040 mi
Registration #9	2017-01-31	81.911 mi
Registration #10	2017-01-31	81.911 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		10.277 est
Registration #19		10.200 mil





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1748 mm
Height	1411 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1510 kg
Max. allowed weight	1950 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13