





report date: 2024-03-29

General information

Make	BMW
Model	125 320D M SPORT
Colour	Grey
Year of manufacture	2015
Top speed	143 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-11-21

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MC	TC	history	
----	----	---------	--

MOT expiry date	2024-11-29
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	11
Total items failed	8

MOT #11	2023-11-22 09:19
MOT test number	932424148362
Result	✓ Passed
Next expiry date	2024-11-29

MOT #10	2022-11-25 10:57
MOT test number	484356453147
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #9	2021-11-30 12:41
MOT test number	550787955340
Result	✓ Passed

Result		✓ Passed
MOT #8	2	2021-01-07 16:16
MOT test	number	837578711139
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))

CarCheck.co.uk page 3/12



MOT #7 2021-01-07 09:34

MOT test number 616776143825

Result X Failed

Fail Offside Rear Seat belt buckle missing (7.1.2 (d))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2020-01-08 11:15

MOT test number 309433241179

Result ✓ Passed

MOT #5 2020-01-08 11:15

MOT test number 968488231968

Result X Failed

Pass with rectification Rear Tyre has a lump, caused by separation or partial failure of its structure

BOTH. (5.2.3 (d) (ii))

MOT #4 2019-06-19 08:14

MOT test number 926961628887

CarCheck.co.uk page 4/12



MOT #3 2019-05-13 16:14

MOT test number 733484455313

Result X Failed

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Rear Road wheel fractured Alloy wheel is cracked/damage (5.2.2 (a))

Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #2 2018-05-17 12:30

MOT test number 549860140401

Result \rightarrow Passed

Advice Exhaust flexi joint damaged

MOT #1 2018-05-14 08:20

MOT test number 752029624418

Result ★ Failed

Fail Nearside Front Front suspension has excessive play in a track control arm inner bush (2.5.B.2b)

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Exhaust flexi joint damaged

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

PROFESSOR	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK NIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-06-12
Last registration	2023-11-22
Complete history	See info



Registration #1	2015-06-12	23 mi
Registration #2	2018-05-14	65.945 mi
Registration #3	2018-05-17	65.948 mi
Registration #4	2019-05-13	86.402 mi
Registration #5	2019-06-19	88.303 mi
Registration #6	2020-01-08	98.797 mi
Registration #7	2020-01-08	98.797 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		71.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1441 mm
Length	4624 mm
Wheel base	2810 mm
Kerb weight	1430 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2
Engine number 71109257