





General information

Make	NISSAN
Model	MICRA ACENTA
Colour	Black
Year of manufacture	2017
Top speed	98 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	103 g/km
CO2 label	В







Internet history

Entry	1

Date Pictures 2021-02-03

10

Listing price

View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-06
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #6	2023-06-06 10:08
MOT test number	163112961776
Result	✓ Passed
Next expiry date	2024-06-06
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view scratches	s on screen (3.2 (a) (i))
Advice Nearside Front Lower Suspension arm pin or bush worn but not resultin rear bush (5.3.4 (a) (i))	ng in excessive movement

MOT #5	2023-06-02 10:28
MOT test number	783247492000
Result	🗙 Failed
Minor Windscreen damaged but not adversely affecting driver's view scratches o	n screen (3.2 (a) (i))
FailOffside Front Lower Suspension arm pin or bush excessively worn rear bush,(5.3.4 (a) (i))	de-laminated from arm
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting i rear bush (5.3.4 (a) (i))	n excessive movement





MOT test number 6982184	40201
	40381
Result 🗸	Passed
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice Nearside Rear Nail in tyre	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3		2022-06-03 13:25
MOT test	number	289936388057
Result		🗙 Failed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice Nearside Rear Nail in tyre		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Pass wit	th rectification Offside Windscreen wiper does not clear the windscreen ef	ffectively (3.4 (b) (ii))

MOT #2	2021-06-07 15:27
MOT test number	517498784656
Result	✓ Passed
Advice Nearside Front Shock absorbers light misting of oil or has limited damp	ping effect (5.3.2 (b))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH BUSHES (5.3.4 (a) (i))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in easily BUSHES (5.3.4 (a) (i))	xcessive movement BOTH

MOT #1	2020-11-15 08:10
MOT test number	332410949056
Result	✓ Passed



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 June 2024	Expires: 6 June 2024
Tax status	Valid until 1 June
Days left	32
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 ₩.
Category	 AMPT
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

In miles
8
2017-11-29
2023-06-06
See info



Registration #1	2017-11-29	7 mi
Registration #2	2020-11-15	15.655 mi
Registration #3		11.777 mi
Registration #4	2021-06-07	15.796 mi
Registration #5		11.777 esi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	79%
Pedestrian	79%
Safety systems	72%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1743 mm
Height	1455 mm
Length	3999 mm
Wheel base	2525 mm
Kerb weight	1037 kg
Max. allowed weight	1490 kg
Additional information	
Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11