





report date: 2024-03-28

General information

Make	SUZUKI
Model	CELERIO SZ
Colour	White
Year of manufacture	2015
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-25

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-02
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	7

MOT #8	2023-05-12 11:57
MOT test number	885931916790
Result	✓ Passed
Next expiry date	2024-06-02

MOT #	? 7	2023-05-11 14:11
MOT t	est number	815520792052
Result		🗙 Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Stop lamp(s) all not working (4.3.1 (a) (iii))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	

MOT #6		2022-05-28 11:20
MOT test	number	149220922867
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 2.5mm tread (5.2.3 (c	d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.2mm tread (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2022-05-28 09:42 **MOT test number** 207600293315 Result × Failed Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing 2.5mm tread (5.2.3 (d) (ii)) **Advice Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.2mm tread (5.2.3 (e)) Fail Brake lever has insufficient reserve travel (1.1.2 (a)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e))

MOT #4	2021-06-03 14:34
MOT test number	640579270671
Result	✓ Passed
MOT #3	2020-12-08 13:33

MOT test number	740917590686
Result	✓ Passed

MOT #2	2019-12-09 12:25
MOT test number	525573516236
Result	✓ Passed

MOT #1	2018-12-06 12:22
MOT test number	674821379775
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

NV65RVW

report date: 2024-03-28

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this SUZUKI had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-12-16
Last registration	2023-05-12
Complete history	See info



Registration #1	2015-12-16	27 mi
Registration #2	2018-12-06	18.386 mi
Registration #3	2019-12-09	23.300 mi
Registration #4	2020-12-08	27.391 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		91.777 esi
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1757182

CarCheck.co.uk page 11/11