





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Black
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-17
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	0

MOT #12	2023-10-31 14:21
MOT test number	861537923688
Result	✓ Passed
Next expiry date	2024-11-17

MOI #II	2023-10-27 14:58
MOT test number	371602560431
Result	X Failed

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Headlamp insecure (4.1.1 (c))

MAJOR Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Nearside Headlamp insecure (4.1.1 (c))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

MOT #10 2022-10-29	15:19
--------------------	-------

MOT test number 959432234175

Result ✓ Passed

Advice Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2022-10-29 08:51

MOT test number 543222217291

Result X Failed

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MAJOR Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #8 2021-11-18 15:49

MOT test number 212150667633

MOT #7 2021-03-01 10:49

MOT test number 796655884484

Result \(\sqrt{Passed} \)

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2020-03-09 16:50

MOT test number 875937463538

Result
✓ Passed

MOT #5 2020-03-06 16:06

MOT test number 340928159568

Result X Failed

MAJOR Hazard warning switch inoperative (4.4.2 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4	2019-03-05 15:45
MOT test number	670987075845
Result	✓ Passed
MOT #3	2018-03-06 09:53
MOT test number	363456638499
Result	✓ Passed
MOT #2	2017-02-24 09:02
MOT test number	418738442386
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2016-03-11 14:08
MOT test number	387389710196
Result	✓ Passed

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check

Tax expired: 12 April 2024





Expires: 17 November 2024

Tax status	Expired at 12 April 2024
Days left	16 days too late
MOT expiry date	17 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-04-30
Last registration	2023-10-31
Complete history	See info



Registration #1	2013-04-30	7 mi
Registration #2	2016-03-11	31.294 mi
Registration #3	2017-02-24	37.854 mi
Registration #4	2018-03-06	44.122 mi
Registration #5	2019-03-05	53.324 mi
Registration #6	2020-03-06	58.672 mi
Registration #7	2020-03-09	58.681 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		91.077 mi
Registration #12		0.00 44
Registration #13		9.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



OV13GMU report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	905 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 7401345