



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SOVEREIGN
Colour	Green
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-22
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-05
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	44
Total items failed	16

MOT #22	2023-10-30 12:19
MOT test number	333016078225
Result	✓ Passed
Next expiry date	2024-11-05

MOT #21	2022-10-31 13:16
MOT test number	421433597286
Result	✓ Passed

MOT #20	2021-11-04 15:25
MOT test number	865373906780
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2021-11-04 12:28
MOT test number	537243571153

Result	✗ Failed
--------	----------

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced outer (6.1.1 (c) (i))

**MOT #18**

2020-11-06 13:20

MOT test number

332563151050

Result

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Engine cover and undertrays fitted
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #17

2020-11-05 17:02

MOT test number

153909251166

Result

✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))
- Advice** Engine cover and undertrays fitted
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front tyre wearing on inside edge
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #16**

2019-09-27 17:19

MOT test number

340053237584

Result

✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material both sides (STRONG ADVISE)
(1.1.11 (c))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Covers and under-trays fitted

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #15

2019-09-27 09:27

MOT test number

481660904512

Result

✗ Failed

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall
(5.2.3 (d) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Rear Brake pipe corroded, covered in grease or other material both sides (STRONG ADVISE)
(1.1.11 (c))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Covers and under-trays fitted

MOT #14

2018-10-02 11:41

MOT test number

196265204698

Result

✓ Passed

MOT #13

2017-10-03 08:24

MOT test number

694387804041

Result

✓ Passed

**MOT #12** 2016-10-03 11:03**MOT test number** 311374233975**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #11** 2015-08-06 11:12**MOT test number** 135408315255**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-08-04 10:09**MOT test number** 308166615482**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #9** 2014-07-29 15:09**MOT test number** 626830714283**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-07-29 15:04**MOT test number** 668690514290**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2013-08-06 12:20**MOT test number** 557068113242**Result** ✓ Passed**Advice** Front Trailing arm has slight play in a pin/bush (2.4.G.2)

**MOT #6** 2013-08-02 14:40**MOT test number** 727964913200**Result** ✗ Failed**Fail** Nearside Obligatory mirror does not provide a view to the rear (8.1.2b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Trailing arm has slight play in a pin/bush (2.4.G.2)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-01-15 09:52**MOT test number** 868735613016**Result** ✓ Passed**MOT #4** 2012-01-13 16:21**MOT test number** 935733012090**Result** ✓ Passed**Notice** Front number plate slightly damaged**MOT #3** 2012-01-13 15:42**MOT test number** 849723612086**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Front number plate slightly damaged



MOT #2	2011-01-20 11:52
MOT test number	226590021092
Result	✓ Passed
MOT #1	2010-01-21 14:16
MOT test number	184201120427
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
5 November 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	5 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	BT56WCV
Plate since	2019-09-29
Current registration	BT56WCV
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-01-22
Last registration	2023-10-30
Complete history	See info



Registration #1	2007-01-22	17 mi
Registration #2	2010-01-21	34.667 mi
Registration #3	2011-01-20	44.402 mi
Registration #4	2012-01-13	54.893 mi
Registration #5	2012-01-13	54.893 mi
Registration #6	2013-01-15	63.665 mi
Registration #7	2013-08-02	68.133 mi
Registration #8	2013-08-06	68.138 mi
Registration #9	2014-07-29	74.580 mi
Registration #10	2014-07-29	74.580 mi
Registration #11	2015-08-04	82.894 mi
Registration #12	2015-08-06	82.894 mi
Registration #13	2016-08-06	82.894 mi
Registration #14	2017-08-06	82.894 mi
Registration #15	2018-08-06	82.894 mi
Registration #16	2019-08-06	82.894 mi
Registration #17	2020-08-06	82.894 mi
Registration #18	2021-08-06	82.894 mi
Registration #19	2022-08-06	82.894 mi
Registration #20	2023-08-06	82.894 mi
Registration #21	2024-08-06	82.894 mi
Registration #22	2025-08-06	82.894 mi
Registration #23	2026-08-06	82.894 mi
Registration #24	2027-08-06	82.894 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	070911231434BG