




report date: 2024-03-28

General information

Make	SMART
Model	FORTWO COUPE PASSION 71
Colour	Silver
Year of manufacture	2008
Top speed	90 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	13.3 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-12
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	31
Total items failed	12

MOT #22	2023-11-13 09:22
MOT test number	422740186833
Result	✓ Passed
Next expiry date	2024-12-12
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))

MOT #21	2023-11-13 09:22
MOT test number	454849443810
Result	✗ Failed
Pass with rectification	Horn not working (7.7 (a))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))

MOT #20	2022-12-07 16:38
MOT test number	514846184115
Result	✓ Passed

MOT #19	2021-12-13 12:49
MOT test number	538282061704
Result	✓ Passed

**MOT #18** 2021-12-13 11:47**MOT test number** 420637555690**Result** ✗ Failed**Fail** Fuel cap/sealing device missing seal missing (6.1.3 (b) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #17** 2021-03-26 09:36**MOT test number** 223657974122**Result** ✓ Passed**MOT #16** 2021-03-24 09:14**MOT test number** 140080856745**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))**MOT #15** 2020-04-01 11:40**MOT test number** 958023599990**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14**

2020-03-31 10:25

MOT test number

452854151382

Result**✗ Failed****Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #13**

2019-03-28 12:57

MOT test number

171899380385

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 175/55/15 T (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 155/60/15 T (5.2.3 (e))**Advice** Rear exhaust box corroded and poor condition**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Signs of a engine oil leak**MOT #12**

2019-03-28 12:57

MOT test number

544000688546

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear exhaust box corroded and poor condition**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 175/55/15 T (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 155/60/15 T (5.2.3 (e))**Advice** Signs of a engine oil leak

**MOT #11** 2018-03-28 12:05**MOT test number** 771164164155**Result** ✓ Passed**Advice** Nearside Front tyre worn close to wear bars on inner tread**Advice** Drivers seat belt slow to fully retract**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Fuel cap seal perished**Advice** Offside Front and offside rear tyre valves perished**Advice** Exhaust has a minor leak of exhaust gases rear box (7.1.2)**MOT #10** 2017-03-30 09:42**MOT test number** 507503486015**Result** ✓ Passed**MOT #9** 2016-03-01 10:06**MOT test number** 913794649938**Result** ✓ Passed**MOT #8** 2015-03-17 16:10**MOT test number** 305346475025**Result** ✓ Passed**Notice** Nearside front tyre tread low on the inner edge**MOT #7** 2015-03-17 11:39**MOT test number** 697356875084**Result** ✗ Failed**Notice** Nearside front tyre tread low on the inner edge**Fail** Exhaust system not adequately supported (7.1.1)

**MOT #6** 2014-03-14 17:01**MOT test number** 748853974043**Result** ✓ Passed**MOT #5** 2014-03-13 12:03**MOT test number** 149802074467**Result** ✗ Failed**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2013-03-14 12:12**MOT test number** 277693273073**Result** ✓ Passed**Notice** Nail in nearside front tyre**MOT #3** 2013-03-14 12:12**MOT test number** 205833373002**Result** ✗ Failed**Notice** Nail in nearside front tyre**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #2** 2012-03-15 16:17**MOT test number** 499025472048**Result** ✓ Passed



MOT #12011-03-23 10:55

MOT test number555432481078

Result

✓ Passed

- Notice

Oil leak
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Offside front tyre tread wearing on inner edge
- Notice

Front inner brake pads appear to be becoming low
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Parking brake long travel but has reserve application



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-03-20
Last registration	2023-11-13
Complete history	See info



Registration #1	2008-03-20	20 mi
Registration #2	2011-03-23	23.313 mi
Registration #3	2012-03-15	35.270 mi
Registration #4	2013-03-14	46.593 mi
Registration #5	2014-03-13	59.058 mi
Registration #6	2014-03-14	59.058 mi
Registration #7	2015-03-17	72.046 mi
Registration #8	2015-03-17	72.046 mi
Registration #9	2016-03-01	87.225 mi
Registration #10	2017-03-30	102.672 mi
Registration #11	2018-03-28	108.927 mi
Registration #12	2019-03-28	117.901 mi
Registration #13	2020-03-28	126.875 mi
Registration #14	2021-03-28	135.849 mi
Registration #15	2022-03-28	144.823 mi
Registration #16	2023-03-28	153.797 mi
Registration #17	2024-03-28	162.771 mi
Registration #18	2025-03-28	171.745 mi
Registration #19	2026-03-28	180.719 mi
Registration #20	2027-03-28	189.693 mi
Registration #21	2028-03-28	198.667 mi
Registration #22	2029-03-28	207.641 mi
Registration #23	2030-03-28	216.615 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139