



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN GT TDI DSG DPF 140
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2


Date	2021-08-11
Pictures	33
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-30
Pictures	33
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-26
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	8

MOT #16 2024-02-27 17:46

MOT test number 455014893827

Result ✓ Passed

Next expiry date 2025-02-26

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Washer pipes split**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #15 2023-02-27 14:08

MOT test number 417024252663

Result ✓ Passed**Advice** Front WASHER PIPE SPLIT AND LEAKING BUT WASHERS STILL WORKING

MOT #14 2022-02-23 11:39

MOT test number 342322970808

Result ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-02-22 15:42**MOT test number** 838975909406**Result** ✓ Passed**Advice** Front Inner Tyre worn close to legal limit/worn on edge both fronts inner edges (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #12** 2020-02-26 11:23**MOT test number** 419974973261**Result** ✓ Passed**Advice** Parking brake travel slightly high**MOT #11** 2018-12-22 09:50**MOT test number** 431942880290**Result** ✓ Passed**MOT #10** 2017-12-05 16:59**MOT test number** 657003077384**Result** ✓ Passed**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #9**

2017-12-05 11:35

MOT test number

571680706840

Result**✗ Failed****Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Front Obligatory mirror missing glass (8.1.1)**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8**

2016-12-06 09:59

MOT test number

503306537615

Result**✓ Passed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7**

2016-12-05 11:27

MOT test number

544871802674

Result**✗ Failed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear rear brake binding (3.7.B.1)**MOT #6**

2015-03-18 16:45

MOT test number

438287375094

**MOT #5** 2015-03-18 14:50**MOT test number** 358717575004**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-03-07 12:00**MOT test number** 797976064050**Result** ✓ Passed**MOT #3** 2013-03-01 09:19**MOT test number** 146910163410**Result** ✓ Passed**MOT #2** 2012-03-05 12:24**MOT test number** 958825962048**Result** ✓ Passed**Notice** Wear to o/s/r-n/s/r tyres (inner edges)**MOT #1** 2011-03-12 11:39**MOT test number** 875141571012**Result** ✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 August 2024

✓

MOT

Expires:
26 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KU08KMV
Plate since	2019-06-29
Current registration	 KU08KMV
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-01
Last registration	2024-02-27
Complete history	See info



Registration #1	2008-03-01	18 mi
Registration #2	2011-03-12	25.720 mi
Registration #3	2012-03-05	32.416 mi
Registration #4	2013-03-01	37.775 mi
Registration #5	2014-03-07	44.677 mi
Registration #6	2015-03-18	51.518 mi
Registration #7	2015-03-18	51.518 mi
Registration #8	2016-12-05	60.198 mi
Registration #9	2016-12-06	60.202 mi
Registration #10	2017-12-05	66.695 mi
Registration #11	2018-03-29	75.377 mi
Registration #12	2018-03-29	75.377 mi
Registration #13	2018-03-29	75.377 mi
Registration #14	2018-03-29	75.377 mi
Registration #15	2018-03-29	75.377 mi
Registration #16	2018-03-29	75.377 mi
Registration #17	2018-03-29	75.377 mi
Registration #18	2018-03-29	75.377 mi
Registration #19	2018-03-29	75.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1486 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	BKD C39550