





report date: 2024-03-29

General information

| Make | CITROEN |
|---------------------|---------------------------------------|
| Model | DISPATCH 1000 L1H1 ENTERPRISE P/V HDI |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 90 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-09


Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-06-15 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 6 |
| Failed MOT tests | 4 |
| Total advice items | 10 |
| Total items failed | 9 |

| MOT #10 | 2023-06-02 12:17 |
|---|------------------|
| MOT test number | 978220350947 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-15 |
| Advice Both rear tyres stepping on inner edge | |

MOT test number

Advice

Both rear tyres stepping on inner edge

Advice ### Advice ### Advice ### Advice ### Both rear tyres stepping on inner edge

| MOT #8 | 2022-06-15 10:40 |
|---|---------------------------------|
| MOT test number | 510668562607 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply 60-16 (5.2.3 (d) (i)) | y or cords cut in sidewall 215- |

CarCheck.co.uk page 3/12



× Failed

MOT #7 2022-06-14 11:06

MOT test number 123491843793

Result X Failed

Fail Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Obligatory mirror seriously damaged, affecting the rear view door mirror (3.3 (b) (ii))

Fail Offside Front Position lamp not working side light (4.2.1 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords cut in sidewall 215-60-16 (5.2.3 (d) (i))

Fail Exhaust system insecure all hangers broken (6.1.2 (a))

MOT #6 2021-06-16 08:49

MOT test number 901431446073

MOT #5 2020-09-09 16:20

MOT test number 710131915279

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #4 2020-09-09 08:42

MOT test number 169808383181

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prever

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Result

Advice

CarCheck.co.uk page 4/12



-

MOT #3 2019-08-21 13:04 **MOT test number** 694071616877 Result ✓ Passed MOT #2 2019-08-21 13:04 948504445742 **MOT test number** Result × Failed **Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

| MOT #1 | 2018-05-11 12:05 |
|-----------------|------------------|
| MOT test number | 828847824911 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 215 |
| MOT expiry date | 15 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e when miscory | | |
|--|-----------|-------------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | | EN |
| | | |
| | | |
| | | |
| | | |
| THE STATE OF THE S | | |
| | | |
| *************************************** | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this CITROEN had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2015-03-30 |
| Last registration | 2023-06-02 |
| Complete history | See info |



| 2015-03-30 | 20 mi |
|------------|--|
| 2018-05-11 | 38.228 mi |
| 2019-08-21 | 60.748 mi |
| 2019-08-21 | 60.748 mi |
| 2020-09-09 | 72.854 mi |
| 2020-09-09 | 72.854 mi |
| | 11.777 es |
| | |
| | 2018-05-11 2019-08-21 2019-08-21 2020-09-09 |

More info >

CarCheck.co.uk page 11/12



Dimensions & weight

| Width | 1895 mm |
|---------------------|---------|
| Height | 1942 mm |
| Length | 4805 mm |
| Kerb weight | 1673 kg |
| Max. allowed weight | 2661 kg |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | JBDF0061045 |

CarCheck.co.uk page 12/12