




report date: 2024-03-29

General information

| | |
|---------------------|----------------------------------|
| Make | CITROEN |
| Model | RELAY 35 L2H1 ENTERPRISE BLUEHDI |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 93 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption


| | |
|-------------------------|---------------------|
| Power | 130 BHP |
| Max. torque | 350 Nm at 1.750 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 163 g/km |
| CO2 label | G |





Internet history

| | |
|---------------|-----------------------------|
| Entry 1 | |
| Date | 2021-09-27 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-26 |
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 6 |

| | |
|------------------|--|
| MOT #7 | 2023-10-19 12:53 |
| MOT test number | 810602580954 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-26 |
| Advice | Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) |

| | |
|-----------------|--|
| MOT #6 | 2023-10-18 10:33 |
| MOT test number | 784018135605 |
| Result | ✗ Failed |
| Fail | Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) |
| Advice | Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) |
| Fail | Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |

| | |
|-----------------|---|
| MOT #5 | 2022-10-22 09:52 |
| MOT test number | 424923437817 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge also perished (5.2.3 (e)) |

**MOT #4** 2022-10-21 15:03**MOT test number** 836316316720**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge also perished (5.2.3 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #3** 2021-10-27 15:50**MOT test number** 296130807657**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #2** 2021-03-17 17:15**MOT test number** 460169666330**Result** ✓ Passed**Advice** Nearside Body has damage.**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Mirror outer casing damaged.**MOT #1** 2019-11-15 12:01**MOT test number** 567360445325**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 October 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 26 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2016-11-03 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2016-11-03 | 20 mi |
| Registration #2 | 2019-11-15 | 49.323 mi |
| Registration #3 | 2021-03-17 | 60.415 mi |
| Registration #4 | | |
| Registration #5 | 2021-10-27 | 61.465 mi |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |
| Registration #9 | | |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★ |
| Adult | 59% |
| Children | 86% |
| Pedestrian | 26% |
| Safety systems | 26% |
| Overall rating | 54% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2508 mm |
| Height | 2254 mm |
| Length | 5413 mm |
| Kerb weight | 1900 kg |
| Max. allowed weight | 3500 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 90 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | DYZZ4022162 |