



report date: 2024-03-28

General information

Make	KIA
Model	SOUL CRDI ECHO
Colour	Black
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-14
Pictures	16
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	40
Total items failed	17

MOT #18	2023-09-06 14:17
MOT test number	163656988534
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2023-08-31 15:00
MOT test number	319068348635
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
Advice	Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16**

2022-09-20 16:13

**MOT test number**

584370577743

**Result**

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread Cracked. (0.1 (b))

**MOT #15**

2022-09-12 13:04

**MOT test number**

263386157119

**Result**

✗ Failed

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread Cracked. (0.1 (b))

**MOT #14** 2022-09-05 11:12**MOT test number** 651689425365**Result** ✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Rear Wheel bearing rough when rotated both sides (5.1.3 (b) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #13** 2021-09-10 14:33**MOT test number** 458196759419**Result** ✓ Passed**MOT #12** 2021-04-23 09:32**MOT test number** 440786371255**Result** ✓ Passed**MOT #11** 2021-04-22 12:50**MOT test number** 413999848032**Result** ✗ Failed

- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #10**

2020-04-13 13:01

**MOT test number**

598836879140

**Result**

✓ Passed

- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Hand brake requires very firm pull

**MOT #9**

2020-04-13 09:07

**MOT test number**

843345187360

**Result**

✗ Failed

- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Hand brake requires very firm pull
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #8**

2019-05-02 13:39

**MOT test number**

544214211392

**Result**

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #7** 2019-04-30 13:50**MOT test number** 148071380312**Result** ✗ Failed

- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #6** 2018-05-01 10:32**MOT test number** 221921291405**Result** ✓ Passed

- Advice** Nearside rear brake discs outer face in poor condition
- Advice** Both front tyres close to wear limit
- Advice** Nearside front bottom ball boot split slightly
- Advice** Offside rear brake binding slightly
- Advice** Rear tyres tread cracked

**MOT #5** 2017-05-05 09:12**MOT test number** 749452229736**Result** ✓ Passed

- Advice** Rear brake pads possible close to wear limit
- Advice** All brake flexible hose metal ends slight corrosion



<b>MOT #4</b>	2016-04-22 10:36
---------------	------------------

<b>MOT test number</b>	462102245727
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-05-05 08:26
---------------	------------------

<b>MOT test number</b>	686185825144
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-09-18 10:45
---------------	------------------

<b>MOT test number</b>	519211464238
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2014-09-18 10:45
---------------	------------------

<b>MOT test number</b>	656501464274
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

<b>Pass with rectification</b>	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	---





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
19 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	19 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SH61EKB
Plate since	2019-09-29
Current registration	SH61EKB
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-11-30
Last registration	2023-09-06
Complete history	<a href="#">See info</a>



Registration #1	2011-11-30	25 mi
Registration #2	2014-09-18	5.969 mi
Registration #3	2015-05-05	7.468 mi
Registration #4	2016-04-22	19.514 mi
Registration #5	2017-05-05	33.079 mi
Registration #6	2018-05-01	47.999 mi
Registration #7	2019-04-30	60.713 mi
Registration #8	2019-05-02	60.719 mi
Registration #9	2020-04-13	71.221 mi
Registration #10	2020-04-13	71.221 mi
Registration #11	2020-04-13	71.221 mi
Registration #12	2020-04-13	71.221 mi
Registration #13	2020-04-13	71.221 mi
Registration #14	2020-04-13	71.221 mi
Registration #15	2020-04-13	71.221 mi
Registration #16	2020-04-13	71.221 mi
Registration #17	2020-04-13	71.221 mi
Registration #18	2020-04-13	71.221 mi
Registration #19	2020-04-13	71.221 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1429 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FBBH537175