




report date: 2024-03-28

General information

Make	MAZDA
Model	6 TAMURA
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	184 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-17
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-11
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	37
Total items failed	5

MOT #21	2023-11-07 11:38
MOT test number	954286736774
Result	✓ Passed
Next expiry date	2024-11-11
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #20	2022-11-09 08:19
MOT test number	275631646349
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Play in steering rack inner joint(s)
Advice	Front Tyre worn close to legal limit/worn on edge OS+NS (5.2.3 (e))

**MOT #19**

2022-11-02 09:58

MOT test number

147765291224

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge OS+NS (5.2.3 (e))
- Advice** Offside Play in steering rack inner joint(s)

MOT #18

2021-10-29 08:28

MOT test number

428154980274

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2020-11-05 08:54

MOT test number

127274477931

Result**✓ Passed**

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front brake discs lipped
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))



MOT #16

2020-11-04 10:46

MOT test number

466968056006

Result

✗ Failed

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front brake discs lipped

MOT #15

2019-11-09 13:59

MOT test number

901847260212

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2018-11-10 09:36

MOT test number

719746031675

Result

✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13

2018-11-10 09:36

MOT test number

150256276141

Result

✗ Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2017-11-08 09:32**MOT test number** 372041722998**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside rear tyre lower on inner edge**MOT #11** 2016-11-11 15:10**MOT test number** 844241120572**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2016-11-11 15:10**MOT test number** 120278240064**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2015-11-12 15:06**MOT test number** 259192267955**Result** ✓ Passed

**MOT #8** 2015-11-12 11:45**MOT test number** 704663066130**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Fail** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure sidewall. (4.1.D.1b)**MOT #7** 2014-11-10 10:49**MOT test number** 358264214360**Result** ✓ Passed**MOT #6** 2014-11-10 10:49**MOT test number** 469854814362**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2013-11-07 12:41**MOT test number** 449451413450**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-11-07 11:36**MOT test number** 819221813302**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #3	2012-11-01 13:14
MOT test number	345276202306
Result	✓ Passed
MOT #2	2011-11-09 11:13
MOT test number	188723411355
Result	✓ Passed
MOT #1	2010-11-11 10:22
MOT test number	452965010444
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
11 November 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	11 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-08
Last registration	2023-11-07
Complete history	See info



Registration #1	2007-11-08	19 mi
Registration #2	2010-11-11	28.823 mi
Registration #3	2011-11-09	33.728 mi
Registration #4	2012-11-01	39.929 mi
Registration #5	2013-11-07	46.216 mi
Registration #6	2013-11-07	46.216 mi
Registration #7	2014-11-10	52.583 mi
Registration #8	2015-11-12	61.581 mi
Registration #9	2015-11-12	61.589 mi
Registration #10	2016-11-11	69.969 mi
Registration #11	2016-11-11	69.969 mi
Registration #12	2017-11-11	78.349 mi
Registration #13	2017-11-11	78.349 mi
Registration #14	2017-11-11	78.349 mi
Registration #15	2017-11-11	78.349 mi
Registration #16	2017-11-11	78.349 mi
Registration #17	2017-11-11	78.349 mi
Registration #18	2017-11-11	78.349 mi
Registration #19	2017-11-11	78.349 mi
Registration #20	2017-11-11	78.349 mi
Registration #21	2017-11-11	78.349 mi
Registration #22	2017-11-11	78.349 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1435 mm
Length	4690 mm
Wheel base	2675 mm
Kerb weight	1375 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10316922